

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name C. H. Kyte
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 2
4. Location of Well UNIT LETTER <u>0</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>7</u> TOWNSHIP <u>19S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Eunice Monument Eumont Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3701' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Attempt Dual Completion</u> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with rods and pump. Run logs 4028'-2500'. Set RBP at 3745'. WIH with tubing sub, pressure test casing 500#, ok. Perf 3549-53', 3610-14', 3682-86', 3722-26' with (2) 1/2" JHPF. Spot 200 gals 15% NEFE slick HCL 3549'-3726'. Spot 500 gals acid to 3476'. Acidize with 1500 gals acid, (36) RCNB's. ISIP 2200#, avg pres 3350#, AIR 4.8 BPM. Frac with 1000 gals 15% slick acid, 51,000# 20/40 sand, (24) RCNB's, 40,000 gals foam. ISIP 4840#, avg pres 4400#, AIR 15 BPM. Reverse sand to RBP, release RBP and POH. RIH with tubing, PN, nipple with plug in place, packer, circ valve; set packer at 3768.80', bottom of tubing at 4021.08', circ valve at 3735.42'. Circ valve was in open position. RIH with pump and rods; hung well on. Well not pumping; pulled and changed out pump. Well still not pumping. Loaded tubing and long-stroked pump. Pumping 4 BW with 162 MCF gas in 24 hours. Eunice Monument will be TA, Eumont Gas closed in waiting on pipeline connection. Complete after attempting to dual Eunice-Monument and Eumont Gas.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. D. Pite TITLE Area Engineer DATE 9-15-82  
APPROVED BY Eddie W. Long TITLE OIL & GAS INSPECTOR DATE SEP 17 1982  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 16 1982

C.C.D.  
HOBBS OFFICE