## Submit 3 copies to Appropriate District Office State of New Mexico En€

Minerals and Natural Resources Department

District Office	Life Minerals and	Natural Resources Department		Form C-103
<u>DISTRICT I</u>				Revised 1-1-89
P.O. Box 1980, Hobbs, NM 882	240 OIL CONSER	VATION DIVISION	WELL API NO.	
DISTRICT II	P.O.	Box 2088		
P.O. Box Drawer DD, Artesia, NM	<sub>4 88210</sub> Santa Fe, Nev	v Mexico 87504-2088	30 025 05622 5. Indicate Type of Lease	
DISTRICT III			STATE	FEE 🔲
1000 Rio Brazos Rd., Aztec, NM	87410		6. State Oil / Gas Lease No.	, ree []
SUNDRY (DO NOT USE THIS FORM FOR	Y NOTICES AND REPORTS	ON WELL	G4487	
DIFFERENT	RESERVOIR LISE "APPLICATION	DEEPEN OR PLUG BACK TO A	7 Legge Name - U. S.	
(FC	ORM C-101) FOR SUCH PROPO	SALS.)	7. Lease Name or Unit Agreement N STATE -J-	ame
1. Type of Well: OIL WELL	GAS M		101/12-0-	
2. Name of Operator	WELL DOTHER			
TEXAC	O EXPLORATION & PRODUCTION	ON INC	8. Well No.	
3. Address of Operator P.O. BOX 730, HOBBS, NM 88240			4	
4. Well Location	3X 730, HOBBS, NM 88240		9. Pool Name or Wildcat	
ł			EUMONT YATES 7 RVRS QN (P	RO GAS)
Unit LetterC	Feet From The	NORTH Line and 1980	Feet From The 14/507	
Section 17			Line	
	10.51	Range <u>37E</u> NMI	PMLEA_COUN	ITY
11.	10. Elevation (Show whether	or DF, RKB, RT,GR, etc.) 3709' GL		
Chec	k Appropriate Box to Indica	ate Nature of Notice, Report,		
NOTICE OF INTEN	TION TO:	ne Nature of Notice, Report,	or Other Data	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	_   SUE	BSEQUENT REPORT OF:	
TEMPORARILY ABANDON	CHANGE PLANS	REMEDIAL WORK	ALTERING CASING	_
PULL OR ALTER CARNE	CHANGE PLANS	COMMENCE DRILLING OPER	ATION PLUG AND ARANDONIA	
OTHER:		CASING TEST AND CEMENT	JOB []	ENT 🗌
12		OTHER.		-
12. Describe Proposed or Completed	d Operations (Clearly state all		, and material	🛛
12. Describe Proposed or Completed any proposed work) SEE RULE 1	103.	rtinent details, and give pertinent o	dates, including estimated date of	tartina
6/20/94 RU. Kill well. TIH with casing	d scraper and elegands to a second			rei ung
6/21/94 Set and test 1	a soluber and cleaned out to 3680.	тон.		
6/21/94 Set and tested plug @ 3550' to	o 500#. OK. TOH with plug.			
6/22/94 Perforated Euront on interval	3565' - 3600' with 2 ISBE and 50			
6/23/94 Fracture stimulated well will be	3000 Will 2 33FF and 56 F	noles. Set treating packer @ 3452'.		
6/23/94 Fracture stimulated well with 26 RD BJ. Flow well back.	8000 gallons 40# linear gel and 280	000 gallons CO2 and 208940# 12/20	oand	
		12/20	sand.	
6/25/94 Clean out to 3789' with coil tubi				
6/27/94 Kill well. TOH with treating pac	ker and set production posterio			
6/28/94 8 hour test. Flound (20/04 Th	3 and a set production packer @ 3	509'. Swab 4 runs.		
6/28/94 8 hour test. Flowed (32/64, TP	= 30#) 0 bo, 2 bw, 221 mcf. Shu	t in to build sales line.		
	(			
_			1.	
- $1$	_	•	<b>V</b> _	7
hereby certify that the information above is you and complete	lete to me best of my knowledge and belief.	· · ·	$\nabla$	)
SIGNATURE Jalli.	L L	gineering Assistant	V	<del></del>
TYPE OR PRINT NAME Da		o roma vooiotalit	DATE12/6/94	
	arrell J. Carriger	·	<del>-</del>	
This space for State Use)	MAN BY ATTA SEXTON		Telephone No. 397-0426	<del></del>
APPROVED BY	OF A SUPERVISOR		DEC	40.0
CONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE DEC 13	<b>7994</b>

