

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05629
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 2
8. Well No.	3
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. Box 840, Seminole, Texas 79360	
4. Well Location Unit Letter C : 660 Feet From The NORTH Line and 1980 Feet From The WEST Line Section 18 Township 19S Range 37E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: CONVERT TO INJECTION WELL. ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #203  
Plan to:

Order No. R-9596

MIRU PULLING UNIT. MIRU REVERSE UNIT. TOH W/2-7/8" TUBING. TIH W/RBP. SET RBP AT +\-. 3,750'. CIRC. WELL W/WATER. TEST CSG. TO 700 PSIG. TOH W/TBG. ND OLD WELLHEAD. INSTALL 9-5/8" SOW X 7-1/16" 3M CSG. SPOOL (7" SLIPS). INSTALL 7-1/16" 3M X 7-1/16" 3M TBG. SPOOL. NU BOPS. TIH W/TBG. LATCH ONTO RBP. TOH W/TBG. PU & TIH W/6-1/8" BIT, D.C. & TBG. TAG DOD @ 3,985'. CLEAN OUT CAL SEAL TO 4,029'. CLEAN OUT CMT. TO 4,040'. CIRC. BOTTOMS UP. TOH W/TBG. MIRU LOGGERS. TIH W/3-1/8" GRN/CCL FR. 4,040'-3,235'. RDMO LOGGERS. TIH W/2-7/8" TBG. & SONIC HAMMER TOOL. WASH TO TD (4,040') PUMPING 5-6 BPM IN CIRC. MODE. MIRU ACID COMPANY. ACIDIZE FORMATION W/10,750 GALS. 15% HCL ACID THRU SONIC HAMMER. SHEAR DRAIN PLUG ON SONIC HAMMER. SWAB LOAD TO TANK. TOH W/TBG. (LAYING DWN.)  
(CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 05-23-97  
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)  
ORIGINAL SIGNED BY CHRIS WILLIAMS  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY.