

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to (different depth) for such proposals.)
Use "APPLICATION FOR PERMIT—" for such proposals.

NOV 27 10 46 AM '90

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		2. NAME OF OPERATOR Texaco Producing Inc.		3. ADDRESS OF OPERATOR P. O. Box 730 Hobbs, NM 88240		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 760' FSL & 1980' FEL Unit Ltr. O		5. LEASE DESIGNATION AND SERIAL NO. LC034075		6. IF INDIAN, ALLOTTEE OR TRIBE NAME		7. UNIT AGREEMENT NAME		8. FARM OR LEASE NAME Saunders "K" State Gas Com		9. WELL NO. 1		10. FIELD AND POOL, OR WILDCAT Eumont Yates 7 Rvrs Qn		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 18, T-19-S, R-37-E		12. COUNTY OR PARISH Lea		13. STATE NM	
14. PERMIT NO.				15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3697 GR																					

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

X
X

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRU. C/O from 3567- 3577'. TIH w/ RBP and set @ 3400'. Set tension pkr @ 10'. Tstd csg to 3500#. OK.
2. Perfed @ 3428, 29, 40, 42-48, 52, 56-62, 67, 72, 73 (21 int, 42 holes).
3. Acidized w/ 3000 gal 15% NEFE. Max press = 1250# AIR = 8 BPM.
4. Fraced w/ 23,000 gal 40# linear gel, 23,000 gal CO2 and 170,800# 12/20 sand. Max press = 2288# AIR = 30 BPM.
5. Flowed back. Kld well. Cleaned out to 3577'. Ran tbg, pump, rods.
6. OPT 11-18-90 0 BOPD, 13 BWPD, 700 MCFD.

RECEIVED
NOV 27 12 22 PM '90
BUREAU OF LAND MGMT.
HOBBS, NM.

18. I hereby certify that the foregoing is true and correct

SIGNED Larry D. Ridenour

TITLE Engineer's Assistant

DATE 11-26-90

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side