

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-034075

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

C.J. Saunders Fed.

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT
Eunice Monument
Grayburg-San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 18, T19S, R37E

12. COUNTY OR PARISH
Lea

13. STATE
NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

JUL 7 10 58 AM '88

CARLSBAD AREA SUPERINTENDENT

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Texaco Inc.

3. ADDRESS OF OPERATOR

P. O. Box 723, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit Letter J, 1980' FSL, 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3706' DF

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☒

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- TOH w/rods & pump, NU BOP, Tag up, TOH. Tag PBTD 3947'. TIH w/RBP & pkr. Set RBP @ 3800'. Load, Test 4-1/2" csg to 600#, 30 min, Held OK. TOH w/tools.
- TIH w/3-7/8" bit. Clean out OH @ 3939 to 3947'. TOH w/3-3/8" ultra-jet gun, shoot Grayburg OH w/2 SPF @ 3915, 21, 26, 29, 31, 35, 40, 42, 44' (9 int 18 holes). TIH w/4-1/2" pkr. Set pkr @ 3855'. Load BS 500#. Acidize 6-1/4" OH @ 3914-47 w/3500 gal 15% NEFE & 500# RSB. Max Press 3000#, Ave Press 2000#, AIR 4.6 BPM, ISDP 0#.
- Rel. pkr., TOH. Perf 2 JSPI @ 3819, 21, 30, 36, 40, 42, 44, 48, 52, 54, 56, 58, 60, 62, 64, 77, 81, 86, 88, 90, 92, 3901, 04, 06', (24 int. 48 holes). TIH w/4-1/2" RBP & Pkr. Set RBP @ 3910', pkr. @ 3720'. Load BS w/500#. Acidize 4-1/2" csg perfs 3819-3906' w/4500 gal. 15% NEFE & 50 BS & 200# RSB. Max Press 3000#, Avg Press 2000#, AIR 5.3 BPM, ISIP 0. Rel pkr & plug and TOH. TIH w/127 jts 2-3/8" tbg. Btm. MA @ 3937', SN @ 3919'. Run PM on rods. RD. Start PM.
- On 24 hr potential test: PM 520 BNO, 96 BFW, 150 MCF. Prod. prior to workover: 19 BO, 29 BW, 17 MCF.

18. I hereby certify that the foregoing is true and correct 397-3571

SIGNED [Signature] TITLE Hobbs Area Superintendent

DATE June 30, 1988

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

ACCEPTED FOR RECORD

DATE [Signature]
JUL 20 1988

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.