Submit 3 Copies to Appropriate District Office

State of New Mexico .inerals and Natural Resources Department Energ

Form C·103

Revised 1-1-89

<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO		WELL API NO.	
DISTRICT II	P.O. Box 2088 Santa Fe, New Mexico 87504-2088		30-025-05655	
P.O. Drawer DD, Artesia, NM 88210	Salita 1 c, New Mexico	07504-2000	5. Indicate Type of Lease STATE X	FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. B1589-1	
SUNDRY NOT	ICES AND REPORTS ON WEL	LS		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL GAS WELL X WELL OTHER			NORTH MONUMENT G/SA UNIT BLK 6	
2. Name of Operator AMERADA HESS CORPOR	ΣΔΤΙΩΝ		8. Well No.	
3. Address of Operator			9. Pool name or Wildcat	
DRAWER D, MONUMENT, NEW MEXICO 88265			EUNICE MONUMENT G/SA	
4. Well Location Unit Letter F : 198	BO Feet From The NORTH	Line and1980	Feet From The WEST	Line
Section 20	Township 19S Ra		NMPM LEA	County
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)		
(/////////////////////////////////////	Appropriate Pourte Indicate		anamt on Other Date	
NOTICE OF IN	Appropriate Box to Indicate		eport, of Other Data SEQUENT REPORT OF	: .
NOTICE OF IN	TENTION TO.	305	SECOLIAI NEI ONI OI	;
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CAS	ing
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	GOPNS. PLUG AND ABA	NDONMENT
PULL OR ALTER CASING		CASING TEST AND CE	EMENT JOB	
OTHER: DRILL SIDE TRA	ACK HOLE X	OTHER:		
12. Describe Proposed or Completed Oper work) SEE RULE 1103.	rations (Clearly state all pertinent details, a	nd give pertinent dates, inclu	ding estimated date of starting any prop	osed
TOH WITH TUBING. TIH OPENHOLE TO PBTD (395 3866' WITH MTT LOG. WITH 150 BFW AND PRES IF WELLBORE DOES NOT TIH WITH CEMENT RETAI CEMENT WITH 3/4% CFR-	IG UNIT AND REVERSE UNIT I WITH 5 7/8" BIT ON DRI 50'). TOH W/BIT AND TBG RD SCHLUMBERGER. TIH W SSURE TEST CASING TO 500 PASS INTEGRITY TEST. C INER AND TUBING. SET RE -3. (VOLUMES TO BE DETE	LL COLLARS AND ENTER ITH RBP AND SET PSI FOR 30 MINUTAINER AT 3850'ERMINE AFTER EST	2 7/8" TUBING. CLEAN GER. TIH AND LOG OH F AT +/-3850'. CIRCULA UTE CASING INTEGRITY T OCEDURE WILL FOLLOW SQUEEZE OPENHOLE WI ABLISHING AN INJECTION	OUT F/3950' - ATE HOLE CLE/ FEST. NOTE: RU CEMENTER! ITH CLASS 'H N RATE). TOI
TUBING. DRILL OUT RE 4 3/4 BIT, 3 3/4 DOWN WITH DRILLING ASSEMBL SCHLUMBERGER. TIH WI	LING/SIDETRACKING EQUIF ETAINER AND CEMENT TO 38 WHOLE MOTOR AND BENT SUB LY. RU SCHLUMBERGER. T ITH PACKER AND TUBING TO LOAD. SWAB/FLOW TEST W	375' TOH WITH BI 3 ON TUBING. KI 11H AND LOG OH F 3 3850'. ACIDIZ	T AND DRILL COLLARS. CKOFF HOLE AND DRILL 1 /3950' -3866' WITH MT1 E WELL WITH 5000 GAL 1	TIH WITH FO 4000'. TO F LOG. RD L5% NEFE DI
	rue and complete to the best of my knowledge and			
SIGNATURE	hele , Je T	TLE SUPV. ADM. S	SVC. DATE 12	-2-92
TYPE OR PRINT NAME R. L. WI	HEELER, JR.		TELEPHONE N	<u> 505-393-2</u> 14
(This space for State Us@R!GINAL SIGI	NED BY JERRY SEXTON		<i>7</i> 0 F	: 0

____ TILE _

DISTRICT | SUPERVISOR APPROVED BY -

DFC 0.4.83 - DATE -

CONDITIONS OF APPROVAL, IF ANY: