

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05656
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1131-3
7. Lease Name or Unit Agreement Name	
NORTH MONUMENT G/SA UNIT BLK. 6	
8. Well No.	7
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
Amerada Hess Corporation

3. Address of Operator  
P.O. DRAWER D, MONUMENT, NM 88265

4. Well Location  
Unit Letter G : 1980 Feet From The NORTH Line and 1980 Feet From The EAST Line  
Section 20 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK  PLUG AND ABANDON   
 TEMPORARILY ABANDON  CHANGE PLANS   
 PULL OR ALTER CASING   
 OTHER: CONVERT TO INJECTION WELL.

SUBSEQUENT REPORT OF:

REMEDIAL WORK  ALTERING CASING   
 COMMENCE DRILLING OPNS.  PLUG AND ABANDONMENT   
 CASING TEST AND CEMENT JOB   
 OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #607  
 MIRU PULLING UNIT & REVERSE UNIT. ND WH. TOH & LAY DWN RODS & PUMP. ND WH. NU BOP. TOH W/TBG. TIH W/RBP & SET @ +/-500'. INSTALL NEW WH EQUIPMENT. TIH W/TBG. & RETRIEVE RBP. TOH W/RBP. TIH W/BIT, D.C.'S & TBG. CLEAN OUT TO TD @ 3,997'. TOH W/BIT. RU WIRELINE CO. & STRING SHOOT O.H. W/400 GR/FT TO REMOVE BARIUM SCALE. RD WIRELINE. RU SCHLUMBERGER & LOG THE O.H. W/SONIC/CNL/GR TOOLS. TIH W/4" CSG. GUN. PERF. 3,812'-3,864', 2 JSPF, 180 DEG. PHASED HEG CHGS. (52 FEET, 105 TOTAL HOLE). RD SCHLUMBERGER. TIH W/SONIC HAMMER ON TBG. TO TD. RU ACID CO. ACIDIZE WELL W/5,000 GALS. 15% NEFE DI HCL W/3% DP-77MX MICELLAR SOLVENT. TOH W/SONIC HAMMER. TIH W/TBG. & PKR. SET PKR. @ +/-3,750'. SWAB/FLOW BACK LOAD. TOH W/TBG. & PKR. LAYING DWN PROD. TBG. P.U. & TIH W/2-3/8" LINED INJ. TBG. W/INJ. PKR. ND BOP. NU INJ. WH ASSEMBLY. RDMO PULLING UNIT. CLEAN & CLEAR LOCATION. OBTAIN SI BOTTOMHOLE PRESS. BEFORE BEGINNING INJECTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 02-21-96  
 TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use) ORIGINAL SIGNED BY TERRY CEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

FEB 26 1996