

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection	7. Unit Agreement Name
2. Name of Operator Texaco Producing Inc.	8. Farm or Lease Name East Eumont Unit
3. Address of Operator PO Box 728, Hobbs, New Mexico 88240	9. Well No. 80
4. Location of Well UNIT LETTER <u>M</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>810</u> FEET FROM THE <u>West</u> LINE, SECTION <u>26</u> TOWNSHIP <u>19S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or WHDCat Eumont Y-7R-Q
15. Elevation (Show whether DF, RT, GR, etc.) 3603' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE FLANS ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRUPU. Install BOP. TOH with packer at 3654'.
- 2) By wireline, set CIBP at 3650'. With bailer, dump 3.5 sxs. cement on top.
- 3) TIH with workstring to PBTD. Circulate gelled mud. Spot ~~12~~ <sup>20</sup> sxs. cement at 1490'-1590'. TOH.
- 4) Perforate 2 squeeze holes at  $\pm$  1200' above TOC at 1250'.
- 5) With workstring, set cement retainer at  $\pm$  1150'. Establish injection rate into perfs, then cement with 350 sxs. Class "H" cement with 2% CaCl<sub>2</sub>. Attempt to circulate to surface out of bradenhead.
- 6) Spot ~~12~~ <sup>20</sup> sxs. cement at 200'-300'.
- 7) Spot ~~6~~ <sup>12</sup> sxs. cement at 0-50'.
- 8) Install P & A marker. RDPU.

THIS COMPLETION MUST BE NOTICED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  
397-3571

SIGNED J. A. Sexton  
ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

TITLE Hobbs Area Superintendent

DATE Sept. 4, 1987

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE SEP 15 1987

RECEIVED

SEP 11 1987

OCD  
HORN OFFICE