

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-1431	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator JOHN H. HENDRIX		8. Farm or Lease Name STATE "T" BTRY 2	
3. Address of Operator 403 WALL TOWERS WEST MIDLAND, TEXAS 79701		9. Well No. 7	
4. Location of Well UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West 28 LINE, SECTION 19 South RANGE 37 East NMPM.		10. Field and Pool, or Wildcat Eunice Monument	
15. Elevation (Show whether DF, RT, GR, etc.) 3634 DF		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up service unit and pull rods and tubing.
2. Set RTBP at 3795'.
3. Perforate Grayburg formation from 3720' to 3790' with 11 jet shots.
4. Acidize with 5000 gallons 15% LSTNE acid.
5. Swab well to test, retrieve bridge plug, and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paula Pendleton TITLE Accountant DATE 11-1-72

APPROVED BY John D. Dwyer TITLE Controller DATE NOV 1 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 11 1967

PL. UNCLASSIFIED (S. 100)
HARRIS, 1967-1968