

TBG., TAGGED UP @ 3,913', BROKE CIRC. & DRLD. OUT FORMATION TO 3,940'. AT 3,940' THE BIT STOPPED MAKING ANY HOLE. STARTED RECOVERING METAL, WIRE, & RUBBER. MADE APPROX. 8" IN 2 HOURS. TOH W/TBG., D.C.'S & BIT. FOUND SOME TEETH GONE OFF THE INSIDE OF THE BIT CONES. SUSPECT JUNK IN THE HOLE. RAN A SHOE W/A KUTRITE ON THE BTM. ON 6 D.C.'S & 119 JTS. OF TBG. TAGGED BTM. @ 3,941'. BROKE CIRC. W/100 BBLs. FW. CUT OVER THE JUNK TO 3,943' & THE SHOE STARTED STICKING & THE TBG. PLUGGED. TOH W/TBG., D.C.'S & SHOE. RCV'D. WHAT LOOKS LIKE THE TOP OF A SAND PUMP OR DUMP BAILER 4-7/8" x 18" LONG. RAN A NEW SHOE & TAGGED UP @ 3,943'. BROKE CIRC. W/80 BBLs. FW, CUT OVER THE JUNK TO 3,945', TBG. PLUGGED & LOST CIRC. PULLED THE SHOE TO 3,632'. PUMPED 250 BBLs. FW & BROKE CIRC. TAGGED UP ON THE JUNK @ 3,945'. CUT OVER THE JUNK TO 3,955'. RCV'D. FORMATION & STEEL CUTTINGS. TOH W/THE TBG., D.C.'S & SHOE. RAN A 5-3/4" SHOE W/A 6-1/4" KUTRITE OD & 4-3/4" I.D., 1 JT. 5-3/4" WASH PIPE, 1 SET OF 4-3/4" JOHNSON JARS, 6 4-3/4" DRILL COLLARS & 119 JTS. OF TBG. TAGGED UP @ 3,945', BROKE CIRC. W/FW & CUT OVER THE FISH TO 3,958' FOR 13'. HAVE CUT A 4-3/4" FISHING NECK ON THE JUNK. RECOVERING ALOT OF FORMATION. HAVING TROUBLE W/THE SHOT HOLE CAVING IN. HAVING TO WASH OVER SOME OF THE SAME HOLE EACH TIME WE PICK UP OFF THE FISH. CIRC. CLEAN & PULLED THE SHOE UP INTO THE CSG. RAN 11 JTS. OF TBG. & TAGGED UP @ 3,955'. BROKE CIRC. W/100 BBLs. FW. CUT ON THE JUNK W/THE SHOE FOR 2 HRS. DID NOT MAKE ANY HOLE. TOH W/THE TBG. & SHOE. FOUND THE SHOE WAS WORN OUT. TIH W/A NEW SHOE W/6-1/4" KUTRITE OD & 4-7/8" ID ON 1 JT. OF 5-3/4" WASH PIPE, 1 SET OF 4-3/4" JARS, 6 4-3/4" DRILL COLLARS & 120 JTS. OF TBG. TAGGED UP @ 3,955', BROKE CIRC. & CUT OVER THE JUNK TO 3,973'. RCV'D. FORMATION, RUBBER & STEEL CUTTINGS. CIRC. CLEAN & PULLED THE SHOE UP INTO THE CSG. RAN 11 JTS. TBG. & TAGGED UP @ 3,973'. BROKE CIRC. W/FW. CUT OVER THE JUNK TO TD @ 3,978' & CIRC. CLEAN. TOH W/TBG., WASH PIPE & SHOE. RCV'D. APPROX. 25' OF THE BARREL OF A DRILLING BAILER. RAN A SHOE W/KUTRITE OD & 4-7/8" ID ON 1 JT. OF WASH PIPE, 1 SET OF 4-3/4" JARS, 6 4-3/4" D.C.'S, & 120 JTS. TBG. TAGGED BTM. @ 3,978' & PULLED THE SHOE BACK UP INTO THE CSG. THE SHOE DRUG FOR ABOUT 45' IN THE O.H. SUSPECT SOME MORE JUNK LEFT IN THE HOLE. TAGGED UP W/THE SHOE @ 3,976'. CUT OVER THE JUNK TO 3,979'. THE SHOE PLUGGED & LOST CIRC. TOH W/THE SHOE & WASH PIPE. RCV'D THE BTM. OF THE BAILER. HAVE RCV'D. ALL OF THE JUNK FR. THE O.H. SCHLUMBERGER LOGGED THE O.H. FR. 3,961' TO 3,722' W/A SONIC, GAMMA RAY, NEUTRON & CCL. RAN A SONIC HAMMER ON 116 JTS. OF TBG. TO 3,641'. RAN THE SONIC HAMMER TO TD @ 3,978'. KNOX SVCS. PUMPED 50 BBLs. FW @ 5 BPM & 1,250#. WASHED THE O.H. FR. 3,923'-3,978' W/THE SONIC HAMMER. PUMPED 40 BBLs. FW @ 4.9 BPM & 1,350#. WASHED THE O.H. 3,856'-3,923'. PUMPED 40 BBLs. FW @ 4.9 BPM & 1,550#. WASHED THE O.H. FR. 3,793'-3,856'. PUMPED 20 BBLs. FW @ 4.9 BPM & 1,600#. WASHED THE O.H. FR. 3,722'-3,793'. ACIDIZED THE O.H. FR. 3,722'-3,978' W/5,000 GALS. OF 15% NEFE ACID W/1.5% DP-77MX CHEMICAL @ 4.3 AVG. BPM & 1,585#. WASHED THE O.H. W/ACID IN THE SAME 4 STGS. AS ABOVE W/THE SONIC HAMMER. FLUSHED W/22 BBLs. FW & PULLED THE TOOL TO 3,730'. SWABBED WELL. WASHED THE SWAB FREE BUT PULLED THE RUBBER OFF OF ONE SWAB CUP. WAS UNABLE TO GET BACK DWN. W/THE SWAB. TOH W/THE TBG. TO RECOVER THE RUBBER OFF THE SWAB CUP. TIH W/119 JTS. TBG. & SET O.E. @ 3,730'. RAN A NEW ROPE SOCKET. SWABBED WELL. TOH W/TBG. LAID DWN. THE 6 4-3/4" D.C.'S. RAN A 2-3/8" SN, 1 JT. OF 2-7/8" IPC TBG., 8 JTS. OF 2-7/8" TBG., A 7" x 2-7/8" TAC & 117 JTS. OF 2-7/8" TBG. FOR A TOTAL OF 126 JTS. SET THE SN OE @