to Appropriate District Office Form C-103 Energy, Minerals and Natural Resources Department Revised 1-1-59 DISTRICT OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 WELL AM NO. P.O. Box 2088 DISTRICT Santa Fe, New Mexico 87504-2088 30-025-05722 P.O. Drawer DD, Ariesia, NM 88210 5. Indicate Type of Lease DISTRICT III STATE FEE \_\_ 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. A-4096-5 SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: NORTH MONUMENT G/SA UNIT WELL X WELL OTHER BLK. 11 2. Name of Operator & Well No. AMERADA HESS CORPORATION 3. Address of Operator 9. Pool name or Wildow POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265 EUNICE MONUMENT G/SA Well Location Unit Letter C: 660 Foot From The NORTH Line and 1980 Feet From The WEST Line Township Range 37E County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: Amended report fr. original of 10/24 X. OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. NMGSAU #1103 Move in rig up pulling unit, reverse unit and air unit. TOH w/rods and pump. ND wellhead. NU BOP. TOH w/tubing. TIH w/bit and drill out to original TD at 3,960'. TIH w/underreamer, drill collars and tubing and underream f/3,824'-3,960'. TOH w/ underreamer. RD air unit. RU Schlumberger and log the openhole w/Sonic/LDT/CNL/ GR tools. Add perforations from 3,768'-3,824' w/2 JSPF. RD Schlumberger. TIH w/a Sonic Hammer on tubing to TD. RU acid co. Acidize well w/5,000 gals. 15% NEFE DI HCL w/3% DP-77MX Micellar Solvent. TIH w/Sonic Hammer. TIH w/tubing and packer. Set packer at  $\pm 3,700$ '. Swab/flow back load. TOH w/tubing and packer, laying down production tubing. Pick up and TIH w/2 3/8" coated injection tubing w/injection pkr. ND BOP. NU injection wellhead assembly. RD MO pulling unit. Clean and clear location. I bereby certify that the informatical above is true and complete to the best of my knowledge and belief.

SIONATURE .

TYPE OR FRINT NAME

APPRONPD BY .....

(This space for State Use)

CONDITIONS OF APPROVAL, IF ANY:

Terry L. Harve

ORIGINAL SIGNED BY

**GARY WINK** 

FIELD REP II

TIME Sr. Staff Assistant DATE 11-03-94

TELEPHONE NO.

NOV 14 1994

393-2144