Submit 3 Copies to Appropriate

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Ene. Minerals and Natural Resources Department

Form C-103

AUG 02 1994

District C.Th.				Revised 1-1-89
DISTRICT 1 P.O. Box 1980, Hobby, NM 88240	OIL CONSERVATION P.O. Box 2088		WELL API NO.	
DISTRICTI	Santa Fe, New Mexico 8		3002	505733
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III	,		5. Indicate Type of Leas	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease	No.
SUNDRY NO	TICES AND REPORTS ON WELL	C		B-6114
(DO NOT USE THIS FORM FOR PR DIFFERENT RESE (FORM	ROPOSALS TO DRILL OR TO DEEPEN OF PERMICE TO SUBJECT OF SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit A	greement Name
1. Type of Well: Off Well X Well (] ones		NORTH MONUMEN	NT G/SA UNIT
2. Name of Operator AMEDADA HESS CORDODA	TION		8. Well No.	
AMERADA HESS CORPORA 3. Address of Operator	.110N		9. Pool name or Wildcat	
POST OFFICE DRAWER D 4. Well Location	, MONUMENT, NEW MEXICO	88265	EUNICE MONUM	
Unit Letter B : 66	O Feet From The NORTH	Line and1980	Feet From The	EAST Lin
Section 29	Township 198 Rang	se 37E №	IMPM LEA	Const
	10. Elevation (Show whether Di	F. RKB, RT, GR, etc.)		Country
11. Check	Appropriate Box to Indicate N	ature of Notice Po	nort or Other Day	
NOTICE OF IN	TENTION TO:		SEQUENT REPO	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTE	RING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. DPLUC	AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEN	X BOL THEN	_
OTHER:		OTHER:		
12. Describe Proposed or Completed Oper work) SEE RULE 1103.	rations (Clearly state all pertinent details, and	give pertinent dates, includi	ng estimated date of startiv	ug any propused
NMGSAU #1102 04-16	-93 Thru 04-21-93 / 05-23	3-94 Thru 06-16	-94	
2-3/8" tubing for a tagged bottom at 3,9 Baker loc-set RBP on w/tubing and RBP. R worked the bit and s 3,860'. Cleaned up the RBP on 53 jts. o of 125 jts. and set bbls. fresh water, p	rigged up and pulled 141 alled a BOP. Pulled 72 total of 126 jts. Ran a 20'. No fill. TOH w/tul 117 jts. of tubing. Tagan a 3-3/4" bit and a 4-craper through the tight tight spot w/the scraper f 2-3/8" tbg. to 1,649'. the RBP at 3,849'. Star ressured up on the casing	jts. of 2-7/8" 3-3/4" bit on 1 bing and bit. If gged up on a tig 1/2" casing scra spot at 3,620". TOH w/tubing Ran 72 jts. of Tool circulated g to 400 psi. If	tubing and 54 127 jts. of tub Ran a 4-1/2" x ght spot at 3,6 aper on 117 jts. Ran bit and scraper and be 2-7/8" tbg. f	jts. of ping and 2-3/8" 523'. TOH s. tubing and scraper to pit. Ran for a total
SKONATURE SKALL		Sr. Staff Assi	istant	ore <u>0</u> 5-21-94
	erry L. Harvey		<i>5,</i>	LEPHONE NO. 393-2144
(This space for State Use)				333-2144
Time share on American		ORIGINAL SIGNED DISTRICT I S	BY JERRY SEXTON UPERVISOR	Alic A.9 106A

04-16-93 Thru 04-21-93 Continued

9-5/8" intermediate casing at 3.5 BPM and 400 psi. Circulated 10 bbls. fresh water to the pit. Latched onto and released the RBP. TOH w/tbg. and RBP. Ran a 2-3/8" SN, 53 jts. of 2-3/8" tbg. and 73 jts. of 2-7/8" tbg. and tested to 800 psi. Held OK. Set the SN oe at 3,907'. Removed the BOP and installed the wellhead. Ran a 2" x 1-1/4" RWBC 12 x 3 x S x O pump #A-0468 on 159-3/4" rods. Loaded the tbg. w/12 bbls. fresh water and checked the pump action. Pumping. Note: Well did not pass the NMGSAU casing integrity test.

05-23-94 Thru 06-16-94

DA&S Well Service rigged up and pulled the rods, pump and tubing. Picked up and ran a 4-1/2" spear w/a 4.010 grapple of 73 jts. of 2-7/8" tubing. Tagged up on the liner top at 2,317'. Latched onto the liner w/the spear. Pulled to 80,000 psi and worked up and down. Liner did not pull free. TOH w/tubing and spear. Ran a 4-1/2" spear w/a 4.010 grapple, a 4-3/4" stop sub, 3-3/4" bumper sub, 3-3/4" jars, 6 3-1/2" drill collars and 68 jts. of 2-7/8" tubing. Tagged up at 2,308'. Stop would not allow the spear to go into the top liner packer. TOH w/tubing and tools. Ran tools back into the hole without the stop sub. Tagged up at 2,314' being six foot deeper. Spear would not set in the top of the liner packer. TOH w/tubing and tools. Checked w/TIW for the I.D. of the top of the liner packer. Ran a 4-1/2" casing spear w/4.010 grapple, a 5-1/8" stop, 3-3/4" bumper sub, 3-3/4" jars, 6 3-1/2" drill collars and 68 jts. of 2-7/8" tubing. Tagged the liner top at 2,313'. Latched onto the liner. Set jars off to 60,000 psi. Liner did not pull free. TOH w/tbg. and tools. Ran a 6" OD lead block and tagged up on liner top at 2,306'. TOH w/leak block. Impression showed 5-1/2" OD x 5-3/8" ID top of liner hanger. Ran a 5-1/2" casing spear w/a 4.320 grapple, 3-3/4" bumper sub, 3-3/4" jars, 6 3-1/2" drill collars and 68 jts. of 2-7/8" tubing. Tagged up on the fish at 2.308'. Latched onto the fish and set jars off to 60,000 psi. Liner pulled free. TOH w/tubing, tools, liner top hanger, 9 jts. of 4-1/2" casing and bottom liner packer. Laid down 6 3-1/2" drill collars. Ran a 3-3/4" bit on 53 jts. of 2-3/8" tubing and 74 jts. of 2-7/8" tubing. Tagged TD at 3,940'. TOH w/tubing and 3-3/4" bit. Ran a 4-1/2" x 2-3/8" baker model "G" loc-set RBP on 53 jts. of 2-3/8" tubing and 67 jts. of 2-7/8" tubing. Set the plug at 3,750'. TOH w/tubing. Ran a 7" \times 2-7/8" fullbore packer on 114 its. of 2-7/8" tubing and set the packer at 3,585'. Tested the liner top and RBP to 1,500 psi. Held OK. Tested the 7" casing w/the packer and found leaks from 1,833' to 1,114'. Had circulation out the 9-5/8" int. casing through the 7" casing leak from 1,114' to 1,208'. TOH w/tubing and packer. Ran a retrieving head on 53 jts. of 2-3/8" tubing and 67 jts. of 2-7/8" tubing. Latched onto the RBP at 3,750'. TOH w/tbg. and RBP. Rotary Wireline ran a 4-1/2" CIBP and set at 3,740'. Ran a Baker dress off tool on 115 jts. of 2-7/8" tubing and dressed off the top of the 4-1/2" liner at 3,586'. Ran a $7" \times 2-7/8"$ baker fullbore packer on 58 jts. of 2-7/8" tubing and set the packer at 1,833'. Star Tool tested the CIBP to 1,000 psi. Held OK. TOH w/tubing and packer. Ran a spear w/a 7" 24# grapple and pulled 50,000# of tension. Cut off and removed old wellhead down to 9-5/8" int. casing and replaced it with a new one.