NO. OF COPIES RECEIVED		
	+	
DISTRIBUTION		
SANTA FE		
FILE	<u> </u>	
U.S.G.S.		
LAND OFFICE		
OPERATOR		

SUNDRY NOTICES AND REPORTS ON WELLS STATE OF THE WASHINGTON OF TH	NO. OF COPIES REC	EIVED	-			Supersedes	
JUN 12 8 11 MM '67 JUN 12 8 11 MM '67 SENDER OF THE STATE OF THE STA	DISTRIBUTIO	DN		OBBS OF	FICE O. C. C.		
SUNDRY NOTICES AND REPORTS ON WELLS ON A COUNTY OF THE PROPERTY OF A COUNTY OF THE PROPERTY O	SANTA FE		NEM WEXICQ.	OIL CONS	ERVATION COMMISSION	Effective 1	-1-6 5
SUNDRY NOTICES AND REPORTS ON WELLS ON A COUNTY OF THE PROPERTY OF A COUNTY OF THE PROPERTY O	FILE		<u> </u>	12	2 . AM 'S7		
Substitute of South Control Substitute of Substitute of South Control Substitute of Su	U.S.G.S.		J	UNIC	O II Wu di		ype of Lease
SUNDRY NOTICES AND REPORTS ON WELLS OR NOT LEE THAT FAMILY PROVIDES AND REPORTS ON WELLS OR NOT LEE THAT FAMILY PROVIDES AND REPORTS ON WELLS OF THE CLASS AND REPORTS A SEASON PET CLASS AND REPORTS ON WELLS A SEASON PET CLASS AND REPORTS A SEASON PROVIDES A SEASON PET CLASS AND REPORTS STATE 8"00" STATE 8"0	LAND OFFICE					State 🚣	Fee,
SUNDRY NOTICES AND REPORTS ON WELLS	OPERATOR]				
The work of the properties of		SLINDE	OV NOTICES AND DED	ODTS ON	WELLC		111111111111111111111111111111111111111
The work of the properties of	(DO NOT USE	JUNUN THIS FORM FOR PRO USE "APPLICAT	(1 NUTICES AND REP SPOSALS TO DRILL OR TO DEEPE TION FOR PERMIT =" (FORM C-	JK 13 UN .n or Plug e .01) for suc	WCLLS BACK TO A DIFFERENT RESERVOIR. CH PROPOSALS.)		
Answerd Spenter Amerada Petroleum Corporation Amerada Petroleum Corporation Answerd Spenter P.O. Box 668 - Hobbs, New Maxico 4. Location of Well 30	1.					7. Unit Agreen	nent Name
Americal Petroleum Corporation S. Address of Committee P.O. Box 668 - Hobbs, New Maxico A. Location of Notic Entry Bast Line, strings 30 remains 198 range 37E nerve Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SEMESIAL WORK TEUROPARILY ARABON PLUG AND ANALES CALVE CHARGE PLANE CALVE SEMESIAL WORK TEUROPARILY ARABON PLUG AND ANALES CALVE STRING TEST AND CENTRE AND CONTROL OF ANALES CALVE TOTAL BRIDER OF THE STRING CALVE PAUL B 1103. PAUL B 1103. PAUL B 1103. PAUL B 103. PAUL B	WELL X		CTHER-				
P.O. Box 668 - Hobbs, New Maxico 4. Location of Well A 660 FET FROM THE Morth INST 198 AND 660 Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: FET FROM ALVESTING AND AND ADDRESS OF THE MORTH AND THE SUBSEQUENT REPORT OF: FET FROM ALVESTING AND ADDRESS OF THE MORTH AND ADDRESS OF THE STATE COMMITTEE PRICE OF THE STATE OF THE STATE COMMITTEE PRICE OF THE STATE OF THE STATE COMMITTEE PRICE OF THE STATE OF	2. Name of Operator					i i	
P.O. Box 668 — Hobbs, New Mexico 1. Location of Wall Out letter A 660 PET FIRST TO More More More More More More More More							
A 660 FEET FIRM THE MOTHER WORTH LINE ACCION 30 TOWNSHIP 198 THE Best LINE, ACCION 30 TOWNSHIP 198 THE Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: FEET GAM RE MEDIAL WORSE TOWNSHIP TOWNS	· ·		Hobbs New Marico			9. Well No.	
THE East LINE, SCHOOL 30 FORWARD THE LINE STATE AND THE LINE SCHOOL SUBSEQUENT REPORT OF LINE AND	4. Location of Well	10x 000 - 1	HODING, MAN PRATCO			10. Field and	Pool, or Wildcat
THE Bast LINE, RECEION 30 TOWNSHIP 198 RANGE 37E MINES. 15. Elevation (Show whether DP, RT, GR, etc.) 2639¹ DF Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERIAN CARRES PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS 17. Describe Proposed or Completed Describing (Clearly state all periliment details, and give pertained drive, including estimated date of starting any proposed mondy, SEE ROLE 103. Pulled rods, pump & tubing, Ram string shots of 300 grains and 500 grains per foot in CR 3845² to 3958². Ram tubing and actidized CR 3843² to 3970² with 500 gals. 15% ME acid. Ran rods & pump and resumed production. No o'mange in producing status.		A	660	Morth	660	Monume	•
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PEGGAND AND AND AND AND AND AND AND AND AND	UNIT LETTER		FEET FROM THE		LINE AND FE	ET FROM	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PEGGAND AND AND AND AND AND AND AND AND AND	THE	LINE, SECTI	on TOWNSHI	<u>. 19</u>	8 37E	NMPM.	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUS AND ABANDON PLUS ON A-LL CASING CHARGE PLANS CH							
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: DESTORM BEMEDIAL WORK FELIG AND ABANDOU FORTH ABANDOUS AND ABANDOUS FULL OR ALTER CASING FULL OR ALTER C			15. Elevation (Sh			12. County	
Check Appropriate Box 10 Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABILY ARASON PULL OR ALTER SASTING CHANGE PLANS CHANGE PLANS CASING TEST AND CLUSEST JOB OTHER String shot & acid. I 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data, including estimated date of starting any proposed work) SEE NULE 1103. Pulled rods, pump & tubing. Ran string shots of 300 grains and 500 grains per foot in RI 3845' to 3958'. Ran tubing and acidized OH 3843' to 3970' with 500 gals. 15% NE acid. Ran rods & pump and resumed production. No change in producing status.				363	91 DF	Loc	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK	10.	Check	Appropriate Box To In	idicate N	lature of Notice, Report	or Other Data	
OTHER String shet & acid. IT. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent, and give pertinent, and give pertinent details, and give pertinent, and	TEMPORARILY ABANDO	on 📄			COMMENCE DRILLING OPNS.	==	 -
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pulled rods, pump & tubing. Ram string shots of 300 grains and 500 grains per foot in OH 3845' to 3958'. Ram tubing and acidized OH 3843' to 3970' with 500 gals. 15% NE acid. Ran rods & pump and resumed production. No change in producing status. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. PRECORD SY ACCURATE District Superintendent DATE 6-9-67	PULL OR ALTER CASIN	4G	CHANGE PLAN	5	. بیر		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103. Pulled rods, pump & tubing. Ram string shots of 300 grains and 500 grains per foot in CH 3845° to 3958°. Ram tubing and acidized CH 3845° to 3970° with 500 gals. 15% NR acid. Ram rods & pump and resumed production. No change in producing status.				L	OTHER SUFFLING	stiet & acid.	<u>_</u>
Pulled rods, pump & tubing. Ran string shots of 300 grains and 500 grains per foot in OH 3845 to 3958. Ran tubing and acidized OH 3843 to 3970 with 500 gals. 15% NE acid. Ran rods & pump and resumed production. No change in producing status. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED B. J. Liny District Superintendent DATE 6-9-67	OTHER						
APPROVED BY TITLE District Superintendent DATE 6-9-67	pe: 50	r foot in 0 0 gals. 15%	H 3845; to 3958; NE acid. Ran red	Ran to	ubing and acidized	OH 3843 to 397	
CONDITIONS OF APPROVAL, IF ANY:							
	_	0		TITLE D	istrict Superintend		-967
	APPROVED BY	3. Lin	4 Charles	TITLE D	istrict Superintend		-967