

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05774
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name NORTH MONUMENT G/SA UNIT BLK. 15
2. Name of Operator Amerada Hess Corporation	8. Well No. 4
3. Address of Operator P.O. DRAWER D, MONUMENT, NM 88265	9. Pool name or Wildcat EUNICE MONUMENT G/SA
4. Well Location Unit Letter D : 330 Feet From The NORTH Line and 330 Feet From The WEST Line Section 31 Township 19S Range 37E NMPM LEA County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1504 (03-06-96 THRU 03-18-96)

MIRU PRIDE WELL SVC. & STAR TOOL. TOH W/PROD. EQUIP. UNFLANGED WELLHEAD, INSTALLED ADAPTER & BOP. RELEASED TAC. P.U. 1 JT. TBG. & TAGGED FOR FILL. TOH W/TBG., TAC, SN, PERF. SUB, & MUD ANCHOR. TAGGED TD AT 3,933' FOR 2' OF FILL. TIH W/RBP, SN & TBG. SET & GOT OFF RBP AT 2,098'. BROKE OUT RISER ON INT. CSG. & FOUND CMT. TO SURF. ON 9-5/8" X 7" CSG. ANNULUS. LOADED 7" CSG. W/WATER & CIRC. WELLBORE TO DISPLACE OIL & GAS. PRESS. TST'D. CSG. & RBP. HELD OK. TOH W/TBG., SN, & RETRIEVING HEAD. POURED 3 SKS. SAND DWN. CSG. & ALLOWED SAND TO SETTLE ON BP. TIH W/TBG. & LOADED WELLBORE. TOH W/TBG. RMV'D. BOP & ADAPTER. LOAD CSG. & CHK. WELL FOR GAS. INSTALLED NEW WELLHEAD. PRESS. TST'D. SEALS TO 1,500#. INSTALLED BOP. TIH W/RETRIEVING HEAD, SN & TBG. TAGGED SAND @ 2,086'. CIRC. SAND OFF & RELEASED RBP.
(CONTINUED ON PAGE 2)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Terry L. Harvey

TITLE SR. STAFF ASSISTANT

DATE

3-29-96

TYPE OR PRINT NAME

TERRY L. HARVEY

TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: