

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-05796

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-2330-10

7. Lease Name or Unit Agreement Name
NORTH MONUMENT G/SA UNIT
BLK. 16

8. Well No.
12

9. Pool name or Wildcat
EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Amerada Hess Corporation

3. Address of Operator
P.O. DRAWER D, MONUMENT, NM 88265

4. Well Location
Unit Letter L : 1980 Feet From The SOUTH Line and 660 Feet From The WEST Line

Section 32 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1612

MIRU PULLING & REVERSE UNIT. TOH W/RODS & PUMP. ND WELLHEAD. NU BOP. TOH W/TBG. RU SCHLUMBERGER & PERF. W/4" CSG. GUN FR. 3,726'-3,734', 3,740'-3,757', 3,766'-3,774', 3,780'-3,882', 3,934'-3,844' & 3,852'-3,862' W/2 SPF 180 DEG. PHASED (95 FEET, 196 HOLES TOTAL). RD SCHLUMBERGER. RU ACID CO. TIH W/SONIC HAMMER ON TBG. ACIDIZE WELL W/5,000 GALS. 15% NEFE DI HCL W/3% DP-77MX MICELLAR SOLVENT. MOVE TOOL ACROSS PERFS. & O.H. FR. 3,726'-3,899' THROUGHOUT ACID JOB. RD ACID CO. TOH W/SONIC HAMMER. TIH W/TBG. & PKR. SET PKR. @ +/-3,700'. SWAB BACK LOAD. TOH W/TBG. & PKR. TIH W/PROD. TBG. ND BOP. TIH W/RODS & PUMP. NU WELLHEAD. RDMO PULLING UNIT. CLEAN & CLEAR LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 04-08-96

TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE 04-08-96

CONDITIONS OF APPROVAL, IF ANY: