STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	-	
40. 01 (0FIES SCEEVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

DIDITIONS OF APPROVAL, IF ANY:

WO. 07 COP	IES ACCEIVED		CHEKVA	HOW DIVISION			
DISTR	IBUTION	7	P. O. BOX	C 2088		Form C-103 -	
SANTA FE		SAN	TA FE NEW	MEXICO 87501		Revised 10-1-78	
FILE		7				•	
U.S.G.S.		7			Sa. Ind	icate Type of Lease	
LAND OF	FICE	-			Sta	te Fee X	
		·			5. Stat	e Oil & Gas Lease No.	
PERATO		_			3. 5.6.		
	,			·			
	SUND	RY NOTICES AND	REPORTS ON	WELLS			
(DO HOT	USE THIS FORM FOR PR	ROPOSÁLS TO DRILL OR TO	O DEEPEN OR PLUG BA	ACK TO A DIFFERENT RESERVOIR	. ////		
	USE AFFEICK	TION FOR PERMIT 2 (FE	AM C-101) FOR SUC	PROPOSALS.	13 1151	Agreement Name	
en (13)	GAS [7]				/. Om	Agreement Name	
WELL LA	WELL .	OTHER-					
Name of Opera	tor				8, Far	n or Lease Name	
Amerada Hess Corporation						S. Phillips	
		7011				·	
Address of Ope					9.2Well	No.	
Drawer "D	", Monument,	New Mexico 882	265				
Location of We					10 Fig	eld and Pool, or Wildcat	
		1020	Cauth.	1000	1	•	
UNIT LETTER		1980 FEET FROM	THE SOUTH	LINE AND	FEET FROM L LUN	ice-Monument (G/SA)	
	· · · · · · · · · · · · · · · · · · ·				7777		
West		33	19-S	37 - E			
THE	LINE, SECT	TON TO	OWH8HIP	RANGE	имрм.		
7771111	7777111111	. 15. Elevat	ion (Show whether I	DF, RT, GR, etc.)	12, Co	unty ///////	
////////		(11111)			Lea	////////	
7777777	<i>7111111111</i>	71111A					
	Check	Appropriate Box	To Indicate N	ature of Notice, Repor	t or Other Dat	a	
		INTENTION TO:	- 1	•			
**	1101102011	MILMITON 10.	į	30831	EQUENT REPO	RI OF:	
	FTT						
RFORM REMEDIA	AL WORK X	PLUG	AND ABANDON	REMEDIAL WORK		ALTERING CASING	
MPORARILY ABA	woon \square			COMMENCE DRILLING OPHS.	Ħ		
	7				 	PLUG AND ABANDONMENT	
LL OR ALTER CA	raine	CHANG	GE PLANS	CASING TEST AND CEMENT JOB			
				OTHER			
OTHER							
Describe Prop	posed or Completed O	perations (Clearly stat	e all pertinent deta	ils, and give pertinent dates.	including estimate	d date of starting any proposed	
work) SEE RI	ULE 1103.			,	•	and the state of t	
lan To:	Pull rods n	umn and tho	set retrieva	able bridge plug @	37001 and	san w/sand	
1411 101	Dowf 6 E/0	only and cog.;	set retrieve	able bilage blug @	5/00 and (ap w/sanu.	
	rem. 0-5/6	ob csg. oppo	site Graybui	rg San Andres zone	T/35/8 to .	35/9, at	
	3600', 3608'	,3611',3633',3	637 to 3639	',3652',3654 to 36	57' & 3660'	w/2 SPF.	
	Acidize w/20	000 gal. 20% NF	-FF HCl acid	d. Swab test. Se	t retrievah	le hridge	
	nlug @ 3550'	and can w/san	d Done 6	E/O" OD osa space	o recrievad	one from	
	2405 + 2407	and cap w/ San	u. Peri. o-	-5/8" OD csg. oppo:	Site G/SA ZO	one from	
	3495 to 349/	', 3508 to 351	U',3512 to	3514',3520 to 3523'	',3526 to 3	528' and	
	from 3532 to	∍ 3536' w/2 SPF	. Acidize w	/2000 gal. 20% NE-I	FF HCl acid	Swah	
	test Recov	er bridge blug	Re-run the	g., pump and rods	and recure	production	
	TOUGH NECUY	c. birage prag	· ve-rail ché	g., pump and rous o	and resume p	n oduction.	
	•						
			•				
•							
			- <u> </u>			·	
nereby certify	y that the information	spave is true and com	plete to the best of	my knowledge and belief.			
		X1	•				
	110	* // /	Dies	duction Claude		0.6.04	
100	nace	N. CRI	TITLE Pro	duction Clerk	DATE	8-6-84	
ORIGI	NAL SIGNED BY J	ERRY SEXTON				1110	
	DISTRICT I SUPER					AUG 1 0 1984	