## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

<b>48. 87 CAPIES SECTIVES</b>	
DISTRIBUTION	
BANTA FE	
FILE	
U.1.0.5.	
LAND OFFICE -	
OPERATOR	

## OIL CONSERVATION DIVISION

	Р. О. ВО		Form C-103 Revised 10-1-
BANTA FE	SANTA FE, NEW	MEXICO 87501	New York
FILE	4		5a. Indicate Type of Leuse
U.1.O.5.	4		State Fee X
LAND OFFICE -	4		5, State Otl & Gas Lease No.
OPERATOR	J		
# 1. 1 P. F.	NAME OF THE PROPERTY OF	Number 1	mmmmmk
SUNDA	RY NOTICES AND REPORTS ON	MACH TO A DIFFERENT RESERVOIR.	
USE **APPLICAT	TION FOR PERMIT - FORM C-101) FOR SUI	H PROPOSALS.	7, Unit Agreement Name
649			T, CM / J, CC mem / Came
weir Weir X	OTHER.		6. Farm of Lease Lane
vame of Operator			b, ram or Lease hane
W. K. Byrom			J. H. Williams
Address of Operator			9. Well No.
Box 147 - Hobbs	,NM88240		3
ocation of Well			10. Field and Pool, or Wildcat
		NUT AND TOTAL SERVICE	Fumont Ougon (Cog)
UNIT LETTER _N 33	SO FEET PROM THE South	1650	Leaghbly decky byby III
THE - West LINE, SECTI	10H 34 TOWNSHIP 19S	RANGE 37E HMP	<i>~{         </i>
mmmm	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
	13. Exercises (supplement)	2.,, 5,	
	NA NA		l Lea
Check	Appropriate Box To Indicate 1	Nature of Notice, Report or C	Other Data
	NTENTION TO:		NT REPORT OF:
• • •			
RFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
i i i i i i i i i i i i i i i i i i i	7 200	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
MPORARILY ABANDON	·	CASING TEST AND CEMENT JOB	And Alexander
LL OR ALTER CASING	. CHANGE PLANS		
	<del></del>	]	
<del>-</del> .	——————————————————————————————————————	OTHER	
OTHER		]	[
. —	Clark at a disparing de	OTHER	ne estimated date of starting any propo-
Describe Proposed or Completed O	perations (Clearly state all pertinent des	OTHER	ng estimated date of starting any propos
Describe Proposed or Completed O work) SEE RULE 1103.	•	OTHERails, and give pertinent dates, includi	
Describe Proposed or Completed O work) SEE RULE 1103.	•	OTHERails, and give pertinent dates, includi	
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull	ling unit, ran 3546' of 2	otherails, and give pertinent dates, including the thought the control of t	with water,
Describe Proposed or Completed Owork) see Rule 1103.  2-28-83: Rigged pull started mixing cement	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace	tbg. Circulated csg.	with water, n csg at
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and	tbg. Circulated csg. setter lite but hole i	with water, n csg at op leak.
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and s	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement	with water, n csg at op leak. at 2 BPM,
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbscircu	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface,	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe	with water, n csg at op leak. at 2 BPM, d filling
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circurating from the surface.	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfa Western pace setter	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface,	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circurasing from the surface.	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfa Western pace setter	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfa Western pace setter	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfa Western pace setter	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfa Western pace setter	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfa Western pace setter	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfa Western pace setter	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfa Western pace setter	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfa Western pace setter	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfa Western pace setter	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfa Western pace setter	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfa Western pace setter	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated csg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishe cop. Mixed and pumped 4	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfawestern pace setter cleaned location.	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t lite total. Placed marke	tbg. Circulated esg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishes op. Mixed and pumped 4 or at surface. Cut anche	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfawestern pace setter cleaned location.	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t	tbg. Circulated esg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishes op. Mixed and pumped 4 or at surface. Cut anche	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owerk) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfawestern pace setter cleaned location.	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t lite total. Placed marke	tbg. Circulated esg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishes op. Mixed and pumped 4 or at surface. Cut anche	with water, n csg at op leak. at 2 BPM, d filling 25 sacks
Describe Proposed or Completed Owork) SEE RULE 1103.  2-28-83: Rigged pull started mixing cement 3000' started taking Ran tubing back and sweight 13 lbs., circu casing from the surfawestern pace setter cleaned location.	ling unit, ran 3546' of 2 t, mixed 75 sacks of pace cement. Pulled tbg. and started mixing Western's alated cement to surface, ace to within 8" of the t lite total. Placed marke	tbg. Circulated esg. setter lite but hole i ran CIBP at 2850 to st pace setter lite cement pulled tbg and finishes op. Mixed and pumped 4 or at surface. Cut anche	with water, n csg at op leak. at 2 BPM, d filling 25 sacks