Office Energy	State of New Mexico Energy, Minerals and Natural Resources		Form C-10 Revised March 25, 19		
District I 1625 N. French Dr., Hobbs, NM 87240		· - •	WELL API		CVISCO IVIAICII 23, I
District II OII	OII CONSEDVATION DIVISION		30-025-05825		
B11 South First, Artesia, NM 87210 District III 2040 South Pacheco		5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87505		STATE FEE X			
District IV 2040 South Pacheco, Santa Fe, NM 87505		0.000	6. State Oi	l & Gas Lease	
SUNDRY NOTICES AND (DO NOT USE THIS FORM FOR PROPOSALS TO D	REPORTS ON WE	ELLS LOB PLUG BACK TO A	7. Lease N	ame or Unit A	greement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSALS.)	R PERMIT" (FORM C-1	101) FOR SUCH			
1. Type of Well: Oil Well Gas Well Other	er Injection		East Eumon	nt Unit	
2. Name of Operator			8. Well No		
OXY USA WIP Limited Partnership		10246	i	•	
3. Address of Operator		19246		ne or Wildcat	
P.O. Box 50250 Midland, TX 79710-02	250			tes 7Rvr On	
4. Well Location					
	feet from thenc	orth line and	1980 f	eet from the	west lin
	Township 198	Range 37E	NMPM	Cour	ity Lea
10. Elev		DR, RKB, RT, GR, et	c.)	n sun king i	
11 01-1 4		3576′			
11. Check Appropria			-		
NOTICE OF INTENTION	TO:	SUB	SEQUENT	Γ REPORT	OF:
PERFORM REMEDIAL WORK 🔲 PLUG AN	ND ABANDON 🛣	REMEDIAL WORK		☐ ALTE	RING CASING
TEMPORARILY ABANDON CHANGE	PLANS	COMMENCE DRILLI	NG OPNS.		G AND
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB			NDONMENT
COMPLE	ETION	OLIVILITY OOD			
OTHER:		OTHER:			
	ns (Clearly state all p	OTHER:	ve pertinent d wellbore diag	lates, including	s estimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE	ns (Clearly state all p E 1103. For Multiple	OTHER:	ve pertinent d wellbore diag	lates, including	estimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3763 8-5/8" 22.7-24# csg @ 317' W/ 250sb	ns (Clearly state all per 1103. For Multiple 1-3799'	OTHER: Dertinent details, and give Completions: Attach	ve pertinent d wellbore diag	lates, including	estimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250ss 5-1/2" 14# csg @ 3900' W/ 100sx, 7-	ns (Clearly state all per 1103. For Multiple 1-3799' k, 12-1/4" hole, -7/8" hole, TOC-3	OTHER: Dertinent details, and give Completions: Attach	ve pertinent d wellbore diag	lates, including	s estimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250ss 5-1/2" 14# csg @ 3900' W/ 100sx, 7-DV tool @ 1350' w/ 100sx, TOC-990'-	ns (Clearly state all per 1103. For Multiple 1103. For Multiple 1-3799' k, 12-1/4" hole, -7/8" hole, TOC-3	OTHER: Descripent details, and give Completions: Attach	ve pertinent d wellbore diag	lates, including	gestimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250ss 5-1/2" 14# csg @ 3900' W/ 100sx, 7-	ns (Clearly state all per 1103. For Multiple 1103. For Multiple 1-3799' k, 12-1/4" hole, -7/8" hole, TOC-3	OTHER: Descripent details, and give Completions: Attach	ve pertinent d wellbore diag	lates, including	estimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250ss 5-1/2" 14# csg @ 3900' W/ 100sx, 7-DV tool @ 1350' w/ 100sx, TOC-990'-1/86 sqz 300sx @ 705-736', circ	ns (Clearly state all per 1103. For Multiple 1103. For Multiple 1-3799' k, 12-1/4" hole, -7/8" hole, TOC-3 -TS 25sx cant to surf	OTHER: Descripent details, and give Completions: Attach	ve pertinent d wellbore diag	lates, including	estimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250sp 5-1/2" 14# csg @ 3900' W/ 100sx, 7-DV tool @ 1350' w/ 100sx, TOC-990'-1/86 sqz 300sx @ 705-736', circ	ns (Clearly state all per 1103. For Multiple 1103. For Multiple 1-3799' x, 12-1/4" hole, -7/8" hole, TOC-3 -TS 25sx cmt to surf	OTHER: Descripent details, and give Completions: Attach TOC-Circ 323'-Calc	wellbore diag	gram of propos	gestimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250sp 5-1/2" 14# csg @ 3900' W/ 100sx, 7-DV tool @ 1350' w/ 100sx, TOC-990'-1/86 sqz 300sx @ 705-736', circ	as (Clearly state all per 1103. For Multiple 1103. For Multiple 1-3799' 1-	OTHER: Descripent details, and give Completions: Attach TOC-Circ 323'-Calc	wellbore diag	gram of propos	g estimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBID-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250sp 5-1/2" 14# csg @ 3900' W/ 100sx, 7-DV tool @ 1350' w/ 100sx, TOC-990'-1/86 sqz 300sx @ 705-736', circ 1. RIH & set CIBP @ 3711', dump 5sx 2. Perf @ 2755', sqz 35sx cmt to 26 3. M&P 25sx cmt @ 1400-1300'	as (Clearly state all per 1103. For Multiple 1103. For Multiple 1-3799' 1-	OTHER: Descripent details, and give Completions: Attach TOC-Circ 323'-Calc DMMISSION MUST BE PRIOR TO THE BE	E NOTIFIED 2	gram of propos	g estimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250ss 5-1/2" 14# csg @ 3900' W/ 100sx, 7-DV tool @ 1350' w/ 100sx, TOC-990'-1/86 sqz 300sx @ 705-736', circ 1. RIH & set CIBP @ 3711', dump 5sx 2. Perf @ 2755', sqz 35sx cmt to 26 3. M&P 25sx cmt @ 1400-1300' 4. M&P 25sx cmt @ 367-267', WOC-TAG	as (Clearly state all persons). For Multiple 1103. For Multiple 1-3799' k, 12-1/4" hole, 10C-3 TS 25sx cant to surface to 3676' K cant to 3676' HOURS PLUGG	OTHER: Descripent details, and give Completions: Attach TOC-Circ 323'-Calc DMMISSION MUST BE PRIOR TO THE BE ING OPERATIONS FOR	E NOTIFIED 2	gram of propos	estimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250sp 5-1/2" 14# csg @ 3900' W/ 100sx, 7-DV tool @ 1350' w/ 100sx, TOC-990'-1/86 sqz 300sx @ 705-736', circ 1. RIH & set CIBP @ 3711', dump 5sx 2. Perf @ 2755', sqz 35sx cmt to 26 3. M&P 25sx cmt @ 1400-1300' 4. M&P 25sx cmt @ 367-267', WOC-TAG 5. M&P 10sx cmt surface plug	ns (Clearly state all persons). For Multiple 1103. For Multiple 1-3799' x, 12-1/4" hole, 10C-3 TS 25sx cant to surface cant to 3676' x cant to 3676' HOURS PLUGG TO BE A	OTHER: Descriment details, and give Completions: Attach TOC-Circ 323'-Calc DMMISSION MUST BE PRIOR TO THE BE ING OPERATIONS FOR APPROVED.	E NOTIFIED 2 GINNING CORTHE C-10	gram of propos	gestimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250sp 5-1/2" 14# csg @ 3900' W/ 100sx, 7-DV tool @ 1350' w/ 100sx, TOC-990'-1/86 sqz 300sx @ 705-736', circ 1. RIH & set CIBP @ 3711', dump 5sx 2. Perf @ 2755', sqz 35sx cmt to 26 3. M&P 25sx cmt @ 1400-1300' 4. M&P 25sx cmt @ 367-267', WOC-TAG 5. M&P 10sx cmt surface plug	ns (Clearly state all persons). For Multiple 1103. For Multiple 1-3799' x, 12-1/4" hole, 10C-3 TS 25sx cant to surface cant to 3676' x cant to 3676' HOURS PLUGG TO BE A	OTHER: Descriment details, and give Completions: Attach TOC-Circ 323'-Calc DMMISSION MUST BE PRIOR TO THE BE ING OPERATIONS FOR APPROVED.	E NOTIFIED 2 GINNING CORTHE C-10	gram of propos	g estimated date ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250ss 5-1/2" 14# csg @ 3900' W/ 100sx, 7-DV tool @ 1350' w/ 100sx, TOC-990'-1/86 sqz 300sx @ 705-736', circ 1. RIH & set CIBP @ 3711', dump 5sx 2. Perf @ 2755', sqz 35sx cmt to 26 3. M&P 25sx cmt @ 1400-1300' 4. M&P 25sx cmt @ 367-267', WOC-TAG	ns (Clearly state all persons) 1-3799' x, 12-1/4" hole, 1-7/8" hole, TOC-3 TS 25sx cant to surface to 3676' THE CONTROL HOURS TO BE A	OTHER: Descriment details, and give Completions: Attach TOC-Circ 323'-Calc DMMISSION MUST BE PRIOR TO THE BE ING OPERATIONS FOR APPROVED.	ENOTIFIED 2 GINNING C DR THE C-10	gram of propos	ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250so 5-1/2" 14# csg @ 3900' W/ 100sx, 7-DV tool @ 1350' w/ 100sx, TOC-990'-1/86 sqz 300sx @ 705-736', circ 1. RIH & set CIBP @ 3711', chmp 5sx 2. Perf @ 2755', sqz 35sx cmt to 26 3. M&P 25sx cmt @ 1400-1300' 4. M&P 25sx cmt @ 367-267', WOC-TAG 5. M&P 10sx cmt surface plug	ns (Clearly state all persons) 1-3799' x, 12-1/4" hole, 1-7/8" hole, TOC-3 TS 25sx cant to surface to 3676' THE CONTROL HOURS TO BE A	OTHER: Descripent details, and give Completions: Attach TOC-Circ 323'-Calc OMMISSION MUST BE PRIOR TO THE BE ING OPERATIONS FOR APPROVED. my knowledge and belief	E NOTIFIED 2 GINNING CONTROL OR THE C-10	gram of propose 24 0F 03 —— DATE —	ed completion
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3763 8-5/8" 22.7-24# csg @ 317' W/ 250ss 5-1/2" 14# csg @ 3900' W/ 100sx, 7-DV tool @ 1350' w/ 100sx, TOC-990'-1/86 sqz 300sx @ 705-736', circ 1. RIH & set CIBP @ 3711', dump 5sx 2. Perf @ 2755', sqz 35sx cmt to 26 3. M&P 25sx cmt @ 1400-1300' 4. M&P 25sx cmt @ 367-267', WOC-TAG 5. M&P 10sx cmt surface plug	as (Clearly state all persons) 1-3799' 1-3799' 1-378" hole, TOC-3 TS 25sx cant to surfactor as a cont to 3676' 1-355' — TAGHE COHOURS PLUGG TO BE /	OTHER: Destrinent details, and give Completions: Attach TOC-Circ 323'-Calc OMMISSION MUST BE PRIOR TO THE BE ING OPERATIONS FOR APPROVED. my knowledge and belief TE ST. Regulatory F	E NOTIFIED 2 GINNING CONTROL OR THE C-10	24 OF 03 DATE — elephone No.	では、 では、 では、 では、 では、 では、 では、 では、 では、 では、
OTHER: 12. Describe Proposed or Completed Operation of starting any proposed work). SEE RULE or recompilation. TD-3900' PBTD-3815' PERFS-3761 8-5/8" 22.7-24# csg @ 317' W/ 250so 5-1/2" 14# csg @ 3900' W/ 100sx, 7-DV tool @ 1350' w/ 100sx, TOC-990'-1/86 sqz 300sx @ 705-736', circ 1. RIH & set CIBP @ 3711', chmp 5sx 2. Perf @ 2755', sqz 35sx cmt to 26 3. M&P 25sx cmt @ 1400-1300' 4. M&P 25sx cmt @ 1400-1300' 4. M&P 25sx cmt @ 367-267', WOC-TAG 5. M&P 10sx cmt surface plug hereby certify that the information above is true and collision. IGNATURE Type or print name David Stewart	ns (Clearly state all persons) 1-3799' x, 12-1/4" hole, 1-7/8" hole, TOC-3 TS 25sx cant to surface to 3676' THE CONTROL HOURS TO BE A	OTHER: Destrinent details, and give Completions: Attach TOC-Circ 323'-Calc OMMISSION MUST BE PRIOR TO THE BE ING OPERATIONS FOR APPROVED. my knowledge and belief TE ST. Regulatory F	E NOTIFIED 2 GINNING CONTROL OR THE C-10	24 OF 03 DATE — elephone No.	ed completion

OXY USA INC. PROPOSED EAST EUMONT UNIT 83 SEC 34 T19S R37E LEA NM

0.0 - 75.0' CEMENT PLUG 10sx

267.0 - 367.0' CEMENT PLUG 25sx

0.0 - 370.0' 12-1/4" OD HOLE 0.0 - 317.0' CEMENT 250sx-CIRC 0.0 - 317.0' 8-5/8" OD SURF CSG

705.0 - 736.0' SQUEEZE PERFS 1/86 0.0 - 736.0' CEMENT 300sx-1/86

1300.0 - 1400.0' CEMENT PLUG 25sx

370.0 - 3912.0' 7-7/8" OD HOLE 990.0 - 1350.0' CEMENT 100sx-TS 1350.0 - 1350.0' DVTOOL 3323.0 - 3900.0' CEMENT 100sx-Calc 0.0 - 3900.0' 5-1/2" OD PROD CSG

2655.0 - 2755.0' CEMENT PLUG 35sx

2755.0 - 2755.0' SQUEEZE PERFS

3676.0 - 3711.0' CEMENT PLUG 5sx 3711.0 - 3711.0' CIBP

3815.0 - 3815.0' CIBP 8/57

3761.0 - 3799.0' ABANDONED PERFS 3837.0 - 3869.0' ABANDONED PERFS 8/57

TD: 3900'