STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

101 2111 1111 1211		
	<u> </u>	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE	1_	

OIL CONSERVATION DIVISION

Form	C - 1	03	
Revis	e d	10-	1-7

DISTRIBUTION	j	JA 2088	Revis	ed 19-1-
SANTA FE	SANTA FE, NE	W MEXICO 87501		
PILE	7 5 81.1	1_7:16	5a. Indicate Type of Lease	
U.S.O.S.	O+6-NMOCD	A Province	State XXX	Foo _
LAND OFFICE	1-Midland-	1-Engr	5. State Oil & Gas Lease	No.
DZENATON I	1-Foreman-	<u> </u>	E-5553	***
SUNDA	RY NOTICES AND REPORTS OF	N WELLS		
1.	TON FOR PERMIT 2		7. Unit Agreement Name East Eumont Uni	it
WELL WELL WELL	OTHER-		8, Farm or Lease liame	
2. Name of Operator	2017		0.1 2.1 2 2 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	
Getty Oil Compa	arry		9. Well No.	
3. Address of Operator P.O. Box 730, Hobbs, New Mexico 88240		92		
	lobbs / New riells		10. Field and Pool, or Wi	ldcat
4. Location of Well		1000	Eumont Y-7R-Q	
UNIT LETTER F	1980 FEET FROM THE Nort	h LINE AND 1980 FEE	7777777777	7777
	10	275		/////
THE West LINE, SECT	10N 35 TOWNSHIP 19	S RANGE 37E	_ HMPM. ()	
	15. Elevation (Show wheth	her DF, RT, GR, etc.)	12. County	7777
		. 17.	Iea	
	3593' 'DF Appropriate Box To Indicate			~~~~
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CABING OTHER	CHANGE PLANS	COMMENCE ORILLING OPNS. CASING TEST AND CEMENT JQB	PLUG AND ASAN	
17. Describe Proposed or Completed	Operations (Clearly state all pertinent	details, and give pertinent dates, in	icluding estimated date of starting	any propo
1. Clean out with k 2. Set CIBP at 3750 3. Load casing with 4. Spot 10 sxs. cen 5. Spot 25 sxs. cen	oit and scraper. O' (perfs 3791'-3829'). i 10 ppg. salt-gel mud. ment on top of CIBP 3750 ment 1625'-1378' (top saleze holes at 350'. imp cement down casing an	'-3651'. lt = 1500').		. N
	•			
	Approved a ground of TO	CONTROL MOTHER 24 DO THE SIGNINING OF TIONS FOR THE C-103 -		

true and complete to the best of my knowledge and belief. MAY 18 1984 ORIGINAL SIGNED BY JERRY SEXTON

MAY 17 1984
HOEBS C.D.