

Submit 3 Copies
to Appropriate
District Office

District I
P.O. Box 1980, Hobbs, NM 88240

District II
P.O. Drawer DD, Artesia, NM 88210

District III
1000 Rio Brazos Rd. Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

WELL API NO. 30 - 025 - 05842

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-1651

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL ☒ GAS ☐
WELL ☒ WELL ☐ OTHER

2. Name of Operator
OXY USA INC.

3. Address of Operator
P.O. Box 50250 Midland, TX 79710

4. Well Location
Unit Letter D : 330 Feet From The NORTH Line and 990 Feet From The WEST Line
Section 35 Township 19 S Range 37 E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3,599

7. Lease Name or Unit agreement Name

EAST EUMONT UNIT

8. Well No. 86

9. Pool name or Wildcat
EUMONT YATES SVN RVR QN

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3900' PERFS - 3700' - 3828'

MIRU 7/14/93, NDWH NUBOP, RIH & TAG @ 3702'. CIRC HOLE & CLEAN & DRILL OUT TO 3840'. SWAB TEST WELL. RIH W/ 2-7/8" TBG TO 3700'. MIX & PUMP 10SX CL C CMT W/ 3% CACL2 & SPOT PLUG FROM 3700'-3600', POOH, WOC 5HRS. RIH & DID NOT TAG PLUG, M&P 50SX CL C CMT W/ 3% CACL2 & SPOT PLUG FROM 3700'-3200', POOH, WOC. RIH & TAG PLUG @ 3330'. CIRC HOLE W/ MUD-LADDEN FLUID. POOH TO 2803' & SPOT 12SX CMT PLUG. POOH TO 1497' & SPOT 12SX CMT PLUG, POOH. RIH W/ CR & SET @ 290'. EIR @ 4BPM @ 250# & SQUEEZED W/ 250SX CL C CMT W/ 2% CACL2, PO OF CR & DUMP 3SX CMT ON TOP. POOH, NDBOP, SET 10SX CMT SURFACE PLUG. RDPU, INSTALL DRY HOLE MARKER, CLEAN LOCATION, CUT OFF ANCHORS, WELL P&A 7/23/93. WITNESSED BY CHARLES PERRIN - NMOCD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 08 31 93

TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717

(This space for State Use)

APPROVED BY Charles Perrin TITLE OIL & GAS INSPECTOR DATE DEC 13 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEE 0 5 1993

OCD HULL
OFFICE