Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

__ DATE --

TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is proposed to temporarily abandon this well by the following procedures: 1. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes Thereby certify that the isformation above is true and complete to the best of my knowledge and boild. SIGNATURE TITLE ST. Conservation Coordinato Taste 6/14/91	District Office		•	1101696 A-A-V
P.O. Box 2088 Santa Fe, New Mexico 87504-2088 300250587700 30025058700 300250587700 30025058700 30				WELL API NO.
FO. Driver DD. Ancelas. NM 8210 STATE	P.O. Box 2088			
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PRUG BACK TO A DIFFERENT RESERVOR. USE APPLICATION FOR PERMAT (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Well (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Well (Concoc) Inc. 1. Address of Operator Concoc) Inc. 1. Address of Operator Concoc) Inc. 1. To Desta Dr., STE 100W, Midland, TX 79705-4500 Four From The Cast Line and 1980 Foot From The South Line Setup 3 Township 20S Range 37E NMFM Lea County 10. Elevation (Now weather Dr. REB, RT, GR. etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING CASING TEST AND CEMENT JOB COTHER: COMMENCE DRILLING ONS. PLUG AND ABANDON REMEDIAL WORK ALTERING CASING CASING TEST AND CEMENT JOB COTHER: 12. Describe Proposed or Completed Operations (Clearly state all perioren datas), including entimated data of stating any proposed word SEE RULE 1103. 11. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes 11. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes 12. Therefore, We Hoover Therefore The Section of the base of my townwhates and based. Thus St. Conservation Coordinator, Are 6/14/91 Learny wenty that the approximation above is the base of my townwhates and based. Thus St. Conservation Coordinator, Are 6/14/91 Learny wenty that the approximation above is the base of my townwhates and based. Thus St. Conservation Coordinator, Are 6/14/91 Learny wenty that the approximation above is the base of my townwhates and based. Thus St. Conservation Coordinator, Are 6/14/91 Learny wenty that the approximation above is the base of my townwhates and based. Thus St. Conservation Coordinator, Are 6/14/91 Learny wenty the following the base of my townwhat				5. Indicate Type of Lease
CONDENS RO BRIZON Rd. Azec, NM 57410 Condens SUNDRY NOTICES AND REPORTS ON WELLS CONDENS TO DRILL OR TO DEFFEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PENDIT" State A-3 Cas Com	DISTRICT III			
CONDITUSE THIS FORM FOR PROPOSALS TO DRILLOR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVORUM USE PROPURED FOR PERMIT (PORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:	1000 Rio Brazos Rd., Aztec, NM 87410			
DIFFERENT RESERVORL USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: ORL	SUNDRY NOTI	CES AND REPORTS ON W	ELLS	
1. Type of Well: Will OAS WELL OTHER 2. Name of Operator CONOCO, Inc. 3. Address of Operator 10 Desta Dr., STE 100W, Midland, TX 79705-4500 9. Pool name or Wildest Fumont Pool Well Location Unit Letter I : 660 Feet From The East Line and 1980 Feet From The South Line Section 3 Township 20S Range 37E NMFM Lea County 10. Elevation (Show whether Dr. RRB, RT. GR. stc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all periment datas), see RVLE 103. It is proposed to temporarily abandon this well by the following procedures: 1. RIH With 5½" CIBP to 3450" and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes Theory certify that the algorithmic to the boar of my knowledge and beind. Interface W. Hoover Interface In	DIFFERENT RESER	RVOIR. USE "APPLICATION FOR F		
Veil Location Conoco, Inc. 1. Address of Operator Conoco, Inc. 1. Address of Operator 10 Desta Dr, STE 100W, Midland, TX 79705-4500 4. Well Location Unit Later	1. Type of Well:	107,7 011 00011 1101 001 1201,		
Conoco, Inc. 3. Address of Operator 10 Desta Dr., STE 100W, Midland, TX 79705-4500 4. Well Location Unit Letter 1: 660 Feet From The East Line and 1980 Feet From The South Line Section 3 Township 20S Range 37E NMFM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3583¹ 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including entimated date of starting any proposed word) SEE RULE 1103. 1t is proposed to temporarily abandon this well by the following procedures: 1. RIH With 5½" CIBP to 3450¹ and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes Thereby cently that the information above is the lead symptote to the box of my involving and beind. Thereby cently that the information bove is the lead symptote to the box of my involving and beind. Thereby cently that the information bove is the lead symptote to the box of my involving and beind. Thereby cently that the information bove is the lead symptote to the box of my involving and beind. Thereby cently that the information bove is the lead symptote to the box of my involving and beind. Thereby cently that the information bove is the lead symptote to the box of my involving and beind. Thereby cently that the information bove is the lead symptote to the box of my involving and beind. Thereby cently that the information bove is the lead of my involving and beind. Thereby cently the All Polyce Thereby the following procedures: 1. RIH With 5½" CIBP to 3450 of and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes	OIL GAS WELL X	OTHER		
3. Address of Operator 10 Desta Dr., STE 100W, Midland, TX 79705-4500 4. Well Location Unit Letter I : 660 Feet From The East Line and 1980 Feet From The South Line Section 3 Township 20S Range 37E NMFM Lea County 10. Elevation (Show withher Dr. RKB, RT, GR. etc.) GL 3583' 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is proposed to temporarily abandon this well by the following procedures: 1. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes Thereby certify that the subtrimation above is true and symptom to the box of my knowledge and belief. Thereby certify that the subtrimation above is true and symptom to the box of my knowledge and belief. Thereby certify that the subtrimation above is true and symptom to the box of my knowledge and belief. Thereby certify that the subtrimation above is true and symptom to the box of my knowledge and belief. Thereby certify that the subtrimation above is true and symptom to the box of my knowledge and belief. Thereby certify that the subtrimation above is true and symptom to the box of my knowledge and belief. Thereby certify that the subtrimation above is true and symptom to the box of my knowledge and belief. Thereby certify that the subtrimation above is true and symptom to the box of my knowledge and belief. Thereby certify that the subtrimation above is true and symptom to the box of my knowledge and belief. Thereby certify that the subtrimation above is true and symptom to the box of my knowledge and belief. Thereby certify the subtrimation above is true and sympto	·	c.		
Well Locations Unit Letter I 660 Feet From The East Line and 1980 Feet From The South Line	3. Address of Operator			9. Pool name or Wildcat
Township 20S Range 37E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3583¹ 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON GRAND GASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT GRAND GASING TEMPORARILY ABANDON GASING TEST AND CEMENT JOB GOTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is proposed to temporarily abandon this well by the following procedures: 1. RIH With 5½' CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes Thereby certify that the information above is true and complete to the best of my toowledge and belief. Thereby certify that the information above is true and complete to the best of my toowledge and belief. Thereby certify that the information above is true and complete to the best of my toowledge and belief. Thereby certify that the information above is true and complete to the best of my toowledge and belief. Thereby certify that the information above is true and complete to the best of my toowledge and belief. Thereby certify that the information above is true and complete to the best of my toowledge and belief. Thereby certify that the information above is true and complete to the best of my toowledge and belief. Thereby certify that the information above is true and complete to the best of my toowledge and belief. Thereby certify that the information above is true and complete to the best of my toowledge and belief.		E 100W, Midland, TX	79705-4500	Eumont Pool
In Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG ABANDON OPNS. P	Unit Letter I : 660	Feet From TheEast	Line and1980	Feet From The South Line
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is proposed to temporarily abandon this well by the following procedures: 1. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE ST. Conservation Coordinator and the property (OLE) 686	Section 3	Township 20S		NMPM Lea County
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is proposed to temporarily abandon this well by the following procedures: 1. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes Thereby certify that the spformation above is true and complete to the best of my knowledge and boiled. SIONATURE TILL ST. Conservation Coordinator, according 6/14/91 Intention Coordinator, according 6/14/91 Intention Coordinator, according 6/14/91 Intention Coordinator, according 6/14/91 Intention Coordinator, according 6/14/91		10. Elevation (Show wheth		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is proposed to temporarily abandon this well by the following procedures: 1. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes Thereby certify that the sufformation above is true and complete to the best of my knowledge and boild. SIGNATURE THE ST. Conservation Coordinator April 6/14/91 Interpretation Coordinator Coordinato				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is proposed to temporarily abandon this well by the following procedures: 1. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes Thereby certify that the justjormation above is true and complete to the best of my knowledge and belief. SIGNATURE THE ST. Conservation Coordinato Table 6/14/91		••	•	•
CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is proposed to temporarily abandon this well by the following procedures: 1. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes Thereby certify that the justomation above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE JETTY W. Hoover	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is proposed to temporarily abandon this well by the following procedures: 1. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE ST. Conservation Coordinator ATE 6/14/91	TEMPORARILY ABANDON X	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is proposed to temporarily abandon this well by the following procedures: 1. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE TIME Sr. Conservation Coordinator ATE 6/14/91 Jerty W. Hoover	PULL OR ALTER CASING		CASING TEST AND CI	EMENT JOB
It is proposed to temporerily abandon this well by the following procedures: 1. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes The Commission where the NOTIFIED COMMISSION WORK Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Sr. Conservation Coordinator ATE 6/14/91	OTHER:		OTHER:	
1. RIH With 5½" CIBP to 3450' and set it. 2. Load hole with 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes THE COMMENCING MUST BE NOTIFIED THE COMMENCING WORK I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE JETRY W. Hoover	• • • •	ions (Clearly state all pertinent details,	and give pertinent dates, inclu	ding estimated date of starting any proposed
The Company of the Complete to the best of my knowledge and belief. SIGNATURE Jerry W. Hoover Lead Note 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes The Company of the Complete to the best of my knowledge and belief. SIGNATURE Jerry W. Hoover	It is proposed to tem	porarily abandon this	s well by the fol	llowing procedures:
The Company of the Complete to the best of my knowledge and belief. SIGNATURE Jerry W. Hoover Lead Note 125 BBLS packer fluid and pressure test to 500 psi for 30 minutes The Company of the Complete to the best of my knowledge and belief. SIGNATURE Jerry W. Hoover	1. RIH With 5½"	' CIBP to 3450' and se	et it.	
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE SIGNATURE Sr. Conservation Coordinator 6/14/91 Jerry W. Hoover		th 125 BBLS packer f	luid and pressure	e test to 500 psi for 30 minutes
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE SIGNATURE Sr. Conservation Coordinator 6/14/91 Jerry W. Hoover				
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE SIGNATURE Sr. Conservation Coordinator 6/14/91 Jerry W. Hoover				
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE SIGNATURE Sr. Conservation Coordinator 6/14/91 Jerry W. Hoover				
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE SIGNATURE Sr. Conservation Coordinator 6/14/91 Jerry W. Hoover				
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE SIGNATURE Sr. Conservation Coordinator 6/14/91 Jerry W. Hoover			in the second second	Treate and the second
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE SIGNATURE Sr. Conservation Coordinator 6/14/91 Jerry W. Hoover	_ v an e	LARGE DE NOTIFIED		10 Sept 10
SIGNATURE Sr. Conservation Coordinator 6/14/91 Jerry W. Hoover	TE CONTROL	THE COMMERCING W	JKK JA ING	
SIGNATURE Sr. Conservation Coordinator 6/14/91 Jerry W. Hoover	Thereby certify that the information shows in true			
Jerry W. Hoover	(land OM)	s/l		ion Coordinator _{ATE} 6/14/91
	Jerty W. Hoo			TELEPHONE NO. (915) 686-
(This space for State Use)				

APPROVED BY ---