

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator W. K. Byrom	8. Farm or Lease Name J. W. Cooper	
3. Address of Operator Box 147 - Hobbs, N. M. 88240	9. Well No. #1	
4. Location of Well UNIT LETTER <u>B</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>20</u> RANGE <u>37</u> NMPM.	10. Field and Pool, or Wildcat Eunice-Monument G-SA	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-14-75: Ran tbq and spotted 30 sx plug at 3780, pulled tbq and waited 24 hrs on cement to set. Ran CI bridge plug at 3567 & circulated casing with 10# brine water plus 70 sxs brine jell, spotted 10 sx plug on top of CI. Pulled tbq to 1433 & spotted 20 sx plug across top of salt. Placed a 10 sx plug at surface & installed 4" dry hole marker. Did not try to pull 5 1/2" casing.

Verbal permission to plug was given by Joe Raney by phone.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>W. K. Byrom</u>	TITLE <u>Geologist</u>	DATE <u>4-18-75</u>
APPROVED BY <u>Eddie Lea</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>MAR 20 1979</u>
CONDITIONS OF APPROVAL, IF ANY:		