

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B 1167	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Ernie L. Hegwer		Shell State Sec 3
3. Address of Operator		9. Well No.
P.O. Box 1637 Hobbs, N.M.		
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM		Eumont Yates
THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>20S</u> RANGE <u>37E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3575 GR		Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/7/93 MIRU, Drill out to 3630.
5/9/93 Per and acidize 3550 to 3580,
5/10/93 Acidize W/ 4000Gls. 15% NEFE
8/22/93 Frac 3550 to 3580 W/ 30,000 Gls. 50 Quality foam and 110,000 lbs. hickory sand.
8/25/93 Clean out to 3630 W/ air unit, hang well on.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ernie L. Hegwer TITLE Operator DATE 10/20/93

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE OCT 21 1993

CONDITIONS OF APPROVAL, IF ANY: