

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name E. S. Adkins
3. Address of Operator Drawer D, Monument, New Mexico 88265	9. Well No. 1
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>20S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and Pool, or WHdcat Eunice Monument G/SA
11. Elevation (Show whether DF, RT, GR, etc.) 3565' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to pull rods & pump, check for fill & pull tbq., run cement bond log fr. 3821' to 1821', run carbon oxygen log across Grayburg San Andres zone fr. 3821' to 3221', set retrievable bridge plug in 5-1/2" csg. at 3818' & perforate 5-1/2" csg. opposite Grayburg San Andres zone subject to carbon oxygen log, run Halliburton PPI pkr. & tbq. & acidize Grayburg San Andres zone with 1-1/2 bbls. per set of perforations of 15% NE FE HCl acid, recover fluid control valve and standing valve and swab test, replace retrievable bridge plug with cast iron bridge plug, re-run tbq., pump and rods and resume production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. B. Zipser TITLE Supv. Adm. Ser. DATE 1-16-85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JAN 18 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 17 1985

U.S. HOUSE OF REPRESENTATIVES