

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>CITIES SERVICE OIL COMPANY</b> 004571		8. Farm or Lease Name <b>Laughlin</b>
3. Address of Operator <b>P.O. BOX 69, Hobbs, New Mexico 88240</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>J</b> , <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM <b>East</b> THE LINE, SECTION <b>5</b> TOWNSHIP <b>20S</b> RANGE <b>37E</b> NMPM.		10. Field and Pool, or Wildcat <b>Monument Grayburg-SA</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3570 GR</b>		12. County <b>Lea</b>

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3861', PBTD 3696', Monument Grayburg, San Andres. We propose to plug and abandon this well in the following manner:

1. Load hole with mud laden fluid.
2. Spot 50 sack cement plug (250') from PBTD 3696--3446'.
3. Dump 10 sack cement plug in top of 7" casing from ground level to 30'.
4. Reclaim wellhead and install 4" dry hole marker.
5. Clean location of all materials and debris.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED \_\_\_\_\_ TITLE **District Adm. Supervisor** DATE **Nov. 9, 1971**

APPROVED BY **Orig. Signed by Joe D. Ramey Dist. L. Supv.** TITLE \_\_\_\_\_ DATE **NOV 11 1971**

CONDITIONS OF APPROVAL, IF ANY:

FILED

1 1971

OIL CONSERVATION BOARD  
OFFICE