

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Kolfson Oil Company</b>		8. Farm or Lease Name <b>La Jolla</b>
3. Address of Operator <b>3206 Republic National Bank Tower Dallas, Texas</b>		9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>0</b> <b>1280</b> FEET FROM THE <b>East</b> LINE AND <b>610</b> FEET FROM THE <b>South</b> LINE, SECTION <b>5</b> TOWNSHIP <b>20S</b> RANGE <b>37E</b> NMPM.		10. Field and Pool, or Wildcat <b>Permian (C-34)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3576 KB</b>		12. County <b>Lea</b>

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to set bridge plug at 3670' and perforate Graybur  
at following points 3605, 3613, 3632, 3643, and 3656.  
Propose to acidize with 3500 gallons of 15% acid

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* **J. J. Credean**

TITLE Prod. Engr.

DATE 1-15-69

APPROVED BY

*[Signature]* **John W. Runyan**

TITLE

DATE

**JAN 17 1969**

CONDITION OF APPROVAL, IF ANY: