## Submit 3 Copies

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico

Form C-103

DISTRICT I			
:.O. BOX 1980, 110008, 14W. 00240	OX 1980, Hobbs, NM 88240 P.O. Box 2088		WELL API NO. 30-025-05911
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lesse STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		6. State Oil & Gas Lesse No. 033250	
CLINIDDY NOT	ICES AND DEPORTS ON WELL	<u> </u>	\(\(\)\(\)\(\)\(\)\(\)\(\)\(\)\(\)\(\)\
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name BERTHA BARBER	
Type of Well: OAL GAS WELL WELL	OTHER		
Name of Operator		<del> </del>	8. Well Na
Marathon Oil Company			6
Address of Operator			9. Pool name or Wildcat
P.O. Box 552 Midland, T. Well Location	x. 79702		EUMONT (Y-7R-QN)
Unit Latter : 19  Section 5	Feet From The SOUTH  Township 20-S Rans  10. Elevation (Show whether Delivation)	ge 37–E	S60   Feet From The   WEST   Line
	////// GL: 3559 KB: 3570	)	<u> </u>
. Check	Appropriate Box to Indicate N	ature of Notice, R	eport, or Other Data
NOTICE OF IN	TENTION TO:	SUE	SSEQUENT REPORT OF:
RFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
MPORARILY ABANDON X	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
JLL OR ALTER CASING		CASING TEST AND C	EMENT JOB
BIED.	[ ] [		
2. Describe Proposed or Completed Open	ntions (Clearly state all pertinent details, and	OTHER:	iding estimated date of starting any proposed
2. Describe Proposed or Completed Operwork) SEE RULE 1103.  MARATHON OIL COMPANY IS RESOURCED INTENT TO GOOD W/TBG & TAC. SET CIB IOLD & RECORD FOR 30 MIN.	EQUESTING PERMISSION TO TA TH COMMENCE OPERATIONS. MIRU. P @ 3050'. LOAD HOLE W/CHE BLEED OFF PRESSURE. RUN TE	give pertinent dates, including the second with the poor w	HE PROCEDURE OUTLINED BELOW: PUMP. ND WELLHEAD. NU BOP. 2% KCL. TEST CSG TO 500 PSI. ND BOP. NU WELLHEAD. RDMO.
MARATHON OIL COMPANY IS RESOUTEY NMOCD OF INTENT TO COOCH W/TBG & TAC. SET CIB HOLD & RECORD FOR 30 MIN.	EQUESTING PERMISSION TO TA THE COMMENCE OPERATIONS. MIRU. P @ 3050'. LOAD HOLE W/CHE BLEED OFF PRESSURE. RUN TO TA STATUS.	give pertinent dates, including the second with the second with the second seco	HE PROCEDURE OUTLINED BELOW: PUMP. ND WELLHEAD. NU BOP. 2% KCL. TEST CSG TO 500 PSI. ND BOP. NU WELLHEAD. RDMO.