

BERTHA BARBER WELL NO. 6
REESTABLISH EUMONT PRODUCTION

12/15/92 MIRU PU. ND wellhead. NU BOP's. POOH w/2-7/8" tbg & pkr.

12/16/92 RIH w/bit & drill collars on 2-7/8" tbg. DO cement & pushed CIBP to 3429'.

12/17/92 POOH w/bit, drill collars on 2-7/8" tbg. RIH w/pkr on 2-7/8" tbg. Set pkr @ 3097'. Swabbed 2 BW. Well Dry.

12/18/92 Swabbed 3 BW. Well dry.

12/19/92 SDFWE.

12/20/92 SDFWE.

12/21/92 Swabbed 4 BW. Acidized Eumont w/1000 gal HCl acid. Released pkr & POOH w/2-7/8" tbg & pkr. RIH w/2-7/8" tbg.

12/22/92 Swabbed 8 BW.

12/23/92 Swabbed 6 BW. ND BOP's. NU wellhead. RD PU. MOL.