

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.

30-025-05913

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Marathon Oil Company

3. Address of Operator

P.O. Box 2490 Hobbs, NM 88240

4. Well Location

Unit Letter **E** : **1980** Feet From The **North** Line and **660** Feet From The **West** Line

Section **5** Township **20-S** Range **37-E** NMPM **Lea** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

GL 3558' KB 3569'

7. Lease Name or Unit Agreement Name

Bertha Barber

8. Well No.

8

9. Pool name or Wildcat

Eumont; Yates, Seven Rivers

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: **Add Pay, Acidize, and Frac** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/30 MIRU PU. POOH w/pump & rods. ND wellhead. NU BOPE. POOH w/2 3/8" tbg. RIH w/scraper to 3210'. POOH.
7/1 RIH, set CIBP at 3070'. Spot w/20' cmt. RIH w/pkr to 975'. Test, OK. POOH. RIH w/tbg to 3045'.
Pickle w/500 gals 15% acid. Run logs.

7/4 Perf 2430-44', 2462-70, 2484-2502', 2512-18', 2526-34', 2576-86', 2620-30', 2648-60', 2680-90',
2714-24', 2730-34', 2746-60' w/2 SPF. RIH w/RBP & pkr.

7/8 Acidize 2430-2760' w/5000 gals 7 1/2" acid w/350 BS. POOH w/pkr & RBP. RIH w/pkr, set at 2357'. Swab.

7/9 Frac w/98,000 gals 70% CO2 foam w/246,000# 16/30 sand. Flow well.

7/11 Run after frac gamma ray log w/gradient.

7/12 Rel pkr at 2356'. RIH, set 2 3/4" CIBP in 3 1/2" tbg at 2316'. RIH, set pkr at 2357'.

7/14 Blanking plug wouldn't seal off. POOH w/pkr. RIH w/pkr, set at 2362'. RIH w/2 3/8" prod tbg.

7/15 ND BOP. NU wellhead. Pulled blanking plug. RD PU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 7/17/98

TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: