

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-05917 ✓
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 33520
7. Lease Name or Unit Agreement Name BERTHA BARBER
8. Well No. 12
9. Pool name or Wildcat MONUMENT (MCKEE-ELLEN)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL: 3556' KB: 3575'

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Marathon Oil Company
3. Address of Operator P.O. Box 552 Midland, Tx. 79702
4. Well Location Unit Letter L : 1653 Feet From The SOUTH Line and 330 Feet From The WEST Line Section 5 Township 20-S Range 37-E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

02-16-93 NOTIFIED OCD OF INTENT TO START WORK. MIRU. INSTALL BOP. POOH W/108 JTS 2 3/8" TBG. LOADED HOLE.

02-17-93 LOADED HOLE W/10# BRINE W/25#/BBL GEL SET CIBP @ 5100' W/35' CMT ON TOP OF PLUG. CUT 7" CSG @ 2780' AND STARTED OUT OF HOLE.

02-18-93 FINISHED OUT OF HOLE WITH 7" CSG. SET 120 SX CUT PLUG @ 3002. PULLED UP WASHED OFF. TAGGED PLUG @ 2528'.

02-19-93 SET 50 SX CMT PLUG @ 671'. SET CMT PLUG 60' TO SURFACE. CUT OFF WELLHEAD. INSTALLED DRY HOLE MARKER. CLEANED LOCATION. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Thomas M. Price TITLE ENGINEERING TECHNICIAN DATE 03-25-93

TYPE OR PRINT NAME THOMAS M. PRICE TELEPHONE NO. 915-682-1626

(This space for State Use)

APPROVED BY Charlie Ferrin OIL & GAS INSPECTOR DATE SEP 02 1993

CONDITIONS OF APPROVAL, IF ANY:

**RECEIVED**

**MAR 29 1993**

**OCD HOBBS OFFICE**