

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

7. LEASE DESIGNATION AND SERIAL NO.

LC-031621-B

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

UNION TEXAS PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

1300 Wilco Building, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3568' DF

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Britt "B"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Eumont (Queen)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 5, T-20-S, R-37-E

12. COUNTY OR PARISH

13. STATE

Lea

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other) Abandon (Plug)

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRU Well Service Unit. Install BOP.
2. Displace hole w/mud.
3. Set cement plugs as follows:
 - (a). Minimum 35 sx. plug from 2700' to 2900'.
 - (b). Minimum 25 sx. plug from 2400' to 2500'.
 - (c). Minimum 25 sx. plug from 1000' to 1100'.
 - (d). Ten sx. plug at surface.
4. Install dry hole marker.
5. Clean up location as specified on original abandonment authority approved April 12, 1977.

Note: USGS will be notified 24 hours in advance of plugging.

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Sr. Prod. Analyst

DATE 8-16-78

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
AS AMENDED

AUG 22 1978

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side