STATE OF NEW MEXICO ENERGY-AND MINERALS DEPARTMENT

MB. OF COPIES SCCEIFES				
DISTRIBUTION				
BANTA FE				
FILE				
U.S.G.S.				
LAND OFFICE				
OPERATOR		l		

JIL CONSERVATION DIVISIG. P. O. BOX 2088

Form C-103 Povised 19-1-78

DISTRIBUTION	CANTAEFNE	EM MEXICO 97501	K641260 12-1-19	
SANTA PE	SANTA FE, NEW MEXICO 87501 Su. Indicate Type of Lease		Su. Indicate Type of Lesse	
TILE			State Fee X	
U.S.O.S.		•	5. State Oti & Gas Lease No.	
PERATOR			5. State Off & Gas 12 case No.	
			mmmmmm	
SUNDR	Y NOTICES AND REPORTS	ON WELLS		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DELLE ON TO DEFEND OR PLUG SACE TO A DIFFERENT RESERVOIR.				
1.			7. Unit Agreement Name	
OIL X WELL C	OTHER•			
2. Name of Operator		8. Farm or Lease Name		
		L.M. Lambert		
Amerada Hess Corporatio	<u> </u>		9. Well No.	
3. Address of Operator	New Mayica 99265		2	
Drawer "D", Monument, New Mexico 88265			10, Field and Pool, or Wildcat	
4. Location of Well G 1980 FEET FROM THE East LINE AND 1980 FEET FROM			Junice Firmument	
UNIT LETTER	1980 FEET FROM THE Eds C	LINE AND 1980 FEET	THE THE WORLD	
_		27 5		
North Line, SECTION 6 TOWNSHIP 20-S RANGE 37-E NMPM		WAN		
		ec proces	12. County	
	15. Elevation (Show when			
	3571'		Lea (1)1111111	
To. Check	Appropriate Box To Indicat	e Nature of Notice, Report of	r Other Data	
	TENTION TO:	SUBSEQU	JENT REPORT OF:	
NOTICE OF II	TI ENTITION TO			
г	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
PERFORM REMEDIAL WORK	720.0	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT	
TEMPOPARILY ABANDON	CHANGE PLANS	CASING TEST AND CEMENT JOB		
PULL OR ALTER CASING	Change Fenns	OTHER	<u></u>	
Zone abandonm	ant	[X]		
17 Describe Francised or Completed Or	perations (Clearly state all pertinent	details, and give pertinent dates, incl	uding estimated date of starting any proposed	
werk) SEE RULE 1103.				
Dlan to bull 15" tubino	set nlua in 2-3/8"	tubing at 9400'. Cut 2	-3/8" tubing at 9375'.	
Plan to pull 1½" tubing. Set plug in 2-3/8" tubing at 9400'. Cut 2-3/8" tubing at 9375'. Set retrievable bridge plug in 6-5/8" casing at 3800' w/10' sand. Set cement retainer in				
6-5/8" casing at 3650'. Test tubing to 2000# and load annulus and press. to 500#. Squeeze				
aff Charburg Can Andros	: Nil zona thru 6-5/8"	casing. Pert. fr. 3/03	(C) 3/13 W/200 SXS.	
Off Grayburg San Andres	and 100 eye Class "C"	Neat WOC dril out a	nd test. Re-squeeze if	
Class "C" w/additives and 100 sxs. Class "C" Neat. WOC, dril out and test. Re-squeeze if				
necessary. Grayburg-San Andres Oil zone T&A.				
			-	
SET 100 66.	MENT PULL	112 "		
7 / 1/		TE KINER AT	TOP OF CUT POINT	
01-13/8" TUSIN) / _*		237 (872)	
~ 0 / 3 / 10	,			
	<u>.</u>		•	
18. I hereby certify that the information	n above is true and complete to the !	best of my knowledge and belief.	·	
1			44.0.00	
EAG KOI	TITLE	Supv. Adm. Ser.	DATE	
DIENED (CA PEGA				
0 12 15 E	્યા અ∦ 			
Jerry Sex	(Old Title		37A0	
Dist la				
CONDITIONS OF APPROVAL, IF AN	41			