| S STRIBUTION | | Form C-103 Supersedes Old C-102 and C-103 |
|--|---|--|
| FILE NEW MI | EXICO OIL CONSERVATION COMMISSION | Effective 1-1-65 |
| U.S.G.S. | | 5a. Indicate Type of Lease |
| OPERATOR | | State St & Gas Lease No. |
| | | 0.0000 |
| SUNDRY NOTICE | DEFORTS ON WELLS DEFORM OR THIS BACK TO A DIFFERENT RESERVOIR. TO C-1011 FOR SUCH PROPOSALS.) | |
| XIII X STATE OTHER- | | 7. Unit Agreement Name 8. I was or Lease Name |
| Amerada Hess Corporation | | L°M° Lambert |
| Drawer "D", Monument, New Mexi | ico 88265 | 5 |
| NO LETTER G 2314 FEET FROM | | Monument - Blinebry |
| | OWNSHIP 20-S RANGE 37-E NMP | |
| All Is. Elevat | ion (Show whether DF, RT, GR, etc.) 3574 | 12. County Lea |
| Check Appropriate Box NOTICE OF INTENTION TO: | To Indicate Nature of Notice, Report or O | other Data |
| PERFORM REMEDIAL WORK | | |
| TEMPORARILY ABANDON | AND ABANDON REMEDIAL WORK XX COMMENCE DRILLING OPNS. | ALTERING CASING PLUG AND ABANDONMENT |
| PULL OR ALTER CASING CHANG | CASING TEST AND CEMENT JOB | T°A° |
| OTHER | | |
| 17. Describe Fragonei or Completed Operations (Clearly stat work) SEE RULE 1103. | c all pertinent details, and give pertinent dates, includin | g estimated date of starting any proposed |
| on top. Set cast iron b BLINEBRY ZONE P & A Perforated 5-1/2" casing 3584', 3589', 3593', 360 perfs. 3562' to 3617' wi tested. Perforated 5-1/ 3614' to 3618' with one | ent. Set Cast Iron Bridge plug a ridge plug at 3750' with 10' cemend in G-SA zone with 3 shots at: 3566', 3608', 3614', 3617'. Total 306 th 2500 gals. 15% NE acid with ball 2'' casing from 3574', to 3584', 366 (1) shot per foot. Total 19 shots gals. 15% NE acid. Swab tested. | nt on top. 52', 3575', 3579', 50 holes. Acidized 11 sealers. Swab 504' to 3606', and |
| Closed all valves and te | mp. abandoned. | |
| | Experis 8/4 | 1/76 |
| 18. I hereby certify that the information above is true and comp | plete to the best of my knowledge and belief. | |
| SIGNED MIN Colors | Supver., Admin. Services | 7-31-75 |
| | | 1975 |