

Form 6-381a
(March 1942)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 031621-2a
Unit N.I.T.U.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	☒
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

H. F. Britt A-6 No. 4

Hobbs, New Mexico November 28, 1950

Well No. 4 is located 2130 ft. from N line and 520 ft. from W line of sec. 6

3N/4 Sec. 6 20 S 37 E NMPH
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Honamant-Paddock Lee New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3574 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 5 1/2" casing at 5279 and cemented with 382 sacks cement. Total depth of hole 5280 in line. Plug down at 12:00 Midnight 11-21-50. Top cement behind casing 2650 by Temperature Survey.

On 11-24-50, pressure tested casing with 1500# for 30 minutes. Final pressure 1190#. Found top of cement plug at 5229. Drilled out cement plug to 5278 for total depth.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box CC

Hobbs, New Mexico

By L. F. Jacobs

Title Asst. District Superintendent

100-100000
100-100000
100-100000

100-100000

100-100000

100-100000 100-100000 100-100000 100-100000 100-100000 100-100000
100-100000 100-100000 100-100000 100-100000 100-100000 100-100000
100-100000 100-100000 100-100000 100-100000 100-100000 100-100000
100-100000 100-100000 100-100000 100-100000 100-100000 100-100000

100-100000 100-100000 100-100000 100-100000 100-100000 100-100000
100-100000 100-100000 100-100000 100-100000 100-100000 100-100000
100-100000 100-100000 100-100000 100-100000 100-100000 100-100000
100-100000 100-100000 100-100000 100-100000 100-100000 100-100000

100-100000 100-100000

100-100000

100-100000 100-100000

100-100000 100-100000