

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR APPLICATION TO PERMIT OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PURPOSES.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator  
Gulf Oil Corporation

3. Address of Operator  
Box 670, Hobbs, New Mexico 88240

4. Location of Well  
UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 20-S RANGE 37-E N.M.P.M.

7. Unit Agreement Name
8. Farm or Lease Name <u>G. C. Matthews</u>
9. Well No. <u>3</u>
10. Field and Pool, or Wildcat <u>Eunice Monument</u>
12. County <u>Lea</u>

11. Elevation (Show whether DF, KT, GR, etc.)  
3567' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>
Plug and abandon (Revised) <input type="checkbox"/>			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3891' TD, 3723' PB.

Set CI BP at 3650' and cap with 4 sack, 35' cement plug, abandoning perforations 3700' to 3738'. Load hole with abandonment mud. Spot 4 sack, 100' cement plug from 1130' to 1030', across top of salt at 1120'. Spot 6 sack cement plug from 53' to surface. Install dry hole marker and clean location.

OPERATOR MUST BE NOTIFIED 24 HOURS BEFORE TO THE BEGINNING OF OPERATIONS FOR THE C-103

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. F. Berlin TITLE Area Engineer DATE March 4, 1977

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 1977

CONDITIONS OF APPROVAL, IF ANY: See above