

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name J. R. Phillips
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 4
4. Location of Well UNIT LETTER <u>F</u> 1980 FEET FROM THE <u>North</u> LINE AND <u>3300</u> FEET FROM THE <u>East</u> LINE, SECTION <u>6</u> TOWNSHIP <u>20-S</u> RANGE <u>37-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Monument Grayburg San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3567' (GR)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER <u>Squeeze present perfs & reperforate</u> in same zone	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull rods & Pump. Install BOP. Pull tubing.
2. Set cement retainer @ 3675'. Squeeze perfs 3680-3692 W/175 sx Class H Cement. WOC. DOC. Test for 30 minutes, W/600# Tested OK.
3. Perforate 7" Csg W/2-JSPF @ 3652'. From 3656-3660, @3663, from 3665-3669, and @ 3671'.
4. Set pkr. @ 3563'. Acidize perfs 3652-3671 W/2100 gals. 20% NE Acid & 44 Ball Sealers.
5. Perforate 7" Csg W/1-JSPF @ 3620, 24, 27, 29, 41, from 3609-3613 & 3636-3638'.
6. Set pkr. @ 3495' Acidize perfs 3620-3671' W/5000 gals 20% NEFE Acid & 88 ball sealers. Flush W/22 Bbls 2% KCL Water.
7. Install pumping equipment. Test & place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.B. Galt TITLE Dist. Opr. Mgr. DATE 3-5-85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAR - 7 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR -6 1985

0-23
HOMES OFFICE