Submit 3 copies to Appropriate District Office

Ene. ___, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office			11cH3cd 1-1-03
DISTRICT I	OIL CONSERVAT	FION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Box	2088	30-025-05960
P.O. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease
DISTRICT III			STATE FEE .
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil / Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)			7 Lease Name or Unit Agreement Name FHILLIPS, J.R.
1. Type of Well: OIL GAS OTHER			
Name of Operator TEXACO EXPLORATION & PRODUCTION INC.			8. Well No.
3. Address of Operator 205 E. Bender, HOBBS, NM 88240			9. Pool Name or Wildcat EUMONT; YATES-7-RVRS-QUEEN (PRO GAS)
4. Well Location			
Unit Letter <u>E</u> :	2088 Feet From The N	ORTH Line and 660	Feet From The <u>WEST</u> Line
Section 6 Township 20S Range 37E NMPM LEA COUNTY			
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3577' DF			
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTI	ON TO:	SU	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPE	RATION PLUG AND ABANDONMENT
PULL OR ALTER CASING	•	CASING TEST AND CEMEN	IT JOB
OTHER:		OTHER:	Recomplete to Eumont .
9-27-96; MIRU PRIDE, TOH W/ RODS & PUMP, INSTALL BOP &POH W/ TBG. SDFN 9-30-96; TIH W/ CIBP & SET 5050'. CSG TO 500#OK. RU SCHLUMBERGER WL RUN CBL-CNL-GR-CCL. DUMP 35' CEMENT ON TOP OF CIBP. NEW PBTD=5015'. TIH W/ 4" CSG. GUN 120 DEGREE PHASING & PERF EUMONT FORMATION W/2JSPF, 3030'-3260'. TOTAL 230' GROSS,124'NET, 248-52" HOLES. SDFN. 10-1-96; TIH W/PKR TESTED TO 5000#. SET PKR @2967'. ACIDIZE EUMONT PERFS 3030'-3246' W/5000 GALS 15% NE FE HCL & 351 1" BALLS. MAX PRESS=2440#, MIN PRESS=2070#,AIR=7.3BPM,ISDP=130#, 1 MIN=VACUUM. RU SWAB. MADE 3 RUNS &SWABBED DRY. SI. 10-2-96; SWAB, SWABBED DRY. UNSET PKR TOH W/ TBG &PKR.SDFN 10-3-96; TIH W/ PKR. TESTED TO 8000#. SET PKR @ 2916'.INSTALL FRAC TREE. LOAD & TEST BACK/SIDE 500# OK. SDFN 10-4-96; FRAC EUMONT PERFS (3185'-3330') W/60K GAL'S 50 FOAMED 40# LINEAR GEL/C0-2 CARRYING 171K# 12/20 BRADY SAND & TAIL IN W/40K# 12/20 RESIN, PUMPED @ AVG RATE = 40-BPM, AVG PSI= 3500#, MAX PSI= 6100#, ISIP= 1000#, RIG DOWN, START WELL TO FLOWING BACK RECOVERED, 127 BLW. 10-5-96; FLOW WELL 22 HOURS ON VARIOUS CHOKE SIZE'S, RECOVERED 54-BLW. WELL DIED. 10-7-96; PULL & LAY DOWN FRAC TBG & PKR, TIH W/ BIT, CIRCULATE CLEAN. SDON. 10-8-96; TOH W/ BIT & TBG.TIH W/PRODUCTION EQUIPMENT. ND BOP & NU WELLHEAD.TIH W/PUMP & RODS. HUNG ON RDMO. 10-9-96 THRU 12-3-96; PUMPING & TESTING. 12-4-96; OPT 0-BO, 85-BW, 135-MCF.			
TYPE OR PRINT NAME This space for State Use) APPROVED BY	1/	ngineering Assistant	DATE 12/16/96 Telephone No. 397-0432
CONDITIONS OF APPROVAL, IF ANY:	IIILE		DATE DATE
		,	DeSoto/Nichols 12-93 ver 1.0

DeSoto/Nichols 12-93 ver 1.0

1 Part A - 1/