STATE OF NEW MEXICO

ENERGY	AN I MINERALS	DEPARTMENT

THOU MAY THIN TENACO OF	 1 , 4 , 6
NO. OF COMITS HECEIVED	
CISTRIBUTION	
SANTA FE	
FILE	
U.3.0.5.	
LAND OFFICE	
CPENATOR	

HO. OF COMITS HECCEIVED	OIL CONSERVA		Form C-103	
CISTRIBUTION	P. O. BOX 2088		Revised 10-1-78	
SANTA FE	SANTA FE, NEW I	MEXICO 87501	•	
FILE			Sa, Indicate Type of Lease	
U.3.0.8,			State Fee [4]	
LAND OFFICE			5. State Oil & Gas Lease No.	
CPEMATOR			5. State Off & Sus Evuso 110.	
			- Literature Contraction of the	
SUNDRY	NOTICES AND REPORTS ON Y	YELLS		
POSE PROPERTIES FOR OD) USE "SEPPLICATION OF SEPPLICATION OF	DSAUS TO DRILL OR TO DEEPEN OR PLUG BAG H FOR PERMIT — " (FORM C+101) FOR SUCH	CX TO A DIFFERENT RESERVOIR. PROPOSALS.)		
1.			7. Unit Agreement Name	
OIL GAS WELL X	OTHER-			
2. Name of Operator			8. Farm or Lease Name	
<u> </u>			T D Dhilling	
Texaco Inc.			J. R. Phillips	
	00 - 1: -		11	
P.O. Box 728, Hobbs	P.O. Box 728, Hobbs, New Mexico 88240			
4. Location of Well 738			10. Field and Pool, or Wildcat	
UNIT LETTER D 7	36 PEET PROM THE North	LINE AND -736 FEET FROM	Monument Mckee Elle	
West	6 TOWNSHIP 20-	S 37-E		
THE TENE, SECTION	COMNSHIP	NAME		
THE THE THEFT IS	15. Elevation (Show whether D	F, RT, GR, etc.)	12. County	
		' (GR)	I.ea.	
<u>LILLELLECTURE</u>				
Check A	ppropriate Box To Indicate Na	iture of Notice, Report or O	ther Data	
NOTICE OF INT	LENTION TO:	SUBSEQUEN	T REPORT OF:	
				
FERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB		
		OTHER		
OTHER Addl. Perfs. 1	n Mckee Zone			
V. N. A.				
17. Describe Proposed or Completed Ope.	rations (Clearly state all pertinent detai	ls, and give pertinent dates, includin	g estimated date of starting any proposed	
work) SEE RULE 1103.				
1. Rig up. Swab w	all dry			
1. Rig up. Swab w	err dry.			
0 Dansamata 5111 0	In /O TODE from Oli	001 - 05301 05001	- 06041 06641 -	
2. Perforate 5½" 0	sg. w/2-JSPF from 94 9780' and 9791' - 98	001	- 3004 , 3001	
9669', 9771' -	9700, and 9791, - 90	· ·		
3. Swab & Evaluate	! •			
4. Return Well to	production.			
	•			
•				
18. I hereby certify that the information a	sove is true and complete to the best of	my knowledge and belief.		
$(\mathcal{X}_{i}^{\prime})/(\mathcal{X}_{i}^{\prime})$			C == 0=	
SIGNED XVIAILUM	TITLEA	sst. Dist. Manager	DATE 6-30-82	

DATE JUL 2 1982

JERRY SEXTON