

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name Bertha J. Barber
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 17
4. Location of Well UNIT LETTER <u>I</u> , <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>495</u> FEET FROM THE <u>East</u> LINE, SECTION <u>7</u> TOWNSHIP <u>20S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Monument Paddock
15. Elevation (Show whether DF, RT, GR, etc.) 3551' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:



SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 9/11/75 rigged up & installed BOP. POH w/rods, pump & tbq. WIH w/7" cmt retr on 2-3/8" tbq to 5114'. Squeezed perfs 5162-5215' thru retr @ 5114' w/30 sx Cl C Neat cmt, pld out of retr & displaced 20 sx Cl C Neat on top of retr. POH w/tbg. WIH w/2-3/8" OD tbq, tagged TOC @ 5039'. Spotted heavy gelled mud between all plugs. Cut & pld 7" csg from 2512'. Rec 2512' 7" OD 23# csg. WIH w/2-3/8" OD tbq to 2800'. Spotted 75 sk Cl C cmt plug across 9-5/8" OD csg shoe @ 2863' & 7" OD csg shoe @ 2512'. Tagged TOC @ 2350'. OK. Spotted 10 sk cmt plug @ surface & installed regulation dry hole marker. Cleaned & levelled location. P&A effective 9/18/75. Your office to be notified when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE <u>Dist. Drlg. Supv.</u>	DATE <u>9/18/75</u>
APPROVED BY 	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

FEB