* . s	. •.				
NO OF CORIES RECEIVED	F COPIES RECEIVED HIJSES NOT TE B. C. C.				
· · · · · · · · · · · · · · · · · · ·				Form C-103 Supersedes Old	
DISTRIBUTION		C-102 and C-1			
SANTAFE	NEW MEXICO OIL CONS	Effective 1-1-6	5		
Orig&2cc: OCC Hobbs					
LAND OFFICE cc: Regional Office			5a. Indicate Type		
CREBATOR CC: file		State	Fee X		
OPERATOR	cc. IIIe		5, State Oil & Gas	Lease No.	
					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)					
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)					
A11 [77]			7. Unit Agreement Name		
2, Name of Operator	OTHER-		0 5		
Sinclair Oil & Gas Company			8. Form of Lease Name Bertha J. Barber		
1. Address of Operator			9. Well No.		
B. O. Box 1920, Hobbs, New Mexico 88240				17	
4. Location of Well			10, Field and Pool, or Wildcat		
				· · · · · · · · · · · · · · · · · · ·	
UNIT LETTER I , 2310 FEET FROM THE South LINE AND 495 FEET FROM				Monument Blinebry	
heat 77 oog oo					
THE LINE, SECTION 7 TOWNSHIP 20S RANGE 37E NMPM					
mmmmmmm	(61 - 1 - 1	DE DE CO			
	15. Elevation (Show whether	Dr, RI, GR, etc.)	12. County Lea		
			1		
Check A	Appropriate Box To Indicate N	lature of Notice, Report or Ot	her Data		
NOTICE OF IN	TENTION TO:	SUBSEQUEN:	T REPORT OF:		
(-		ļ		_	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERI	NG CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AN	ID ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB			
		OTHER		[_]	
OTHER					
17. Describe Proposed or Completed Op	evotions (Clearly state all pertinent des	gile and give pertinent dates including	actimated data of a	torting any proposed	
work) SEE RULE 163.	elations (decarty state are persment act	and give periment dutes, including	estimated date of si	turting any proposed	
PROPOSE TO: Set Retai	nen @ anner 55251 S	queeze perfs. 5541-5582	1 Donat 2.2 and	A = E(001	
and test	somesse drill out to	56701 and test ampage	Borgrosso	, to 3000.	
Set R P	@ 5570! w/approx 2 sac	5670° and test squeezes. ks cement on top. Perfe	, resqueexe	ii necessary.	
55L1_555	of and acidina w/annor	1000 colo)rate plineor	y approx.	
5541-5559' and acidize w/approx. 1000 gals.					
		,			
	<u> </u>				
18. I hereby certify that the information	above is true and complete to the best	of my knowledge and belief.			
$\mathcal{I} \cap \mathcal{A}$	7				
SIGNED LE	TITLE_	Superintendent	_ DATE2	-8-67	
APPROVED DE	TITLE		DATE		
CONDITIONS OF APPROVAL, IF ANY					