

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410


OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-06015
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No. 014896
Lease Name or Unit Agreement Name BERTIE WHITMIRE
WELL NO. 5
Pool Name or Wildcat LANGLIE MATTIX/MONUMENT BLINDBRY

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
Name of Operator ARCH PETROLEUM INC.	
Address of Operator 10 DESTA DRIVE SUITE 420E	
Well Location Unit Letter F : 1650 Feet From The N Line and 1650 Feet From The W Line 8 Section 20S Township 37E Range NMPM LEA County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3563 GR	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ANBANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
MIRU PU. NDWH NU BOP. SET CIBP @ 5600' CAPPED W/ 35' CMT. DETERMINED FREE PT IN 7" CSG @ 5500'. ND BOP. SHOOT OFF CSG @ 5500'. NU BOP. SET CMT STUB PLUG @ 5500'-50 IN & 50 OUT. SET CMT SHOE PLUG @ 2901'-50 IN & 50 OUT. SET 25 SX CMT PLUG @ 2450, 1400, & 350'. SET 10 SX CMT PLUG @ SURFACE (DISPLACE BETWEEN PLUGS W/ 10# BRINE/ 25# GEL PER BBL MUD). ND BOP & RD PU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE  TITLE SUMMER ENGINEER DATE 07-01-97
TYPE OR PRINT NAME DOUG PARKHURST TELEPHONE NO. 915-685-1961

(This space for State Use)
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JC

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

dps