


DUPLICATE

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico
MISCELLANEOUS REPORTS ON WELLS



Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other) PERFORATING	X

November 27, 1953
(Date)

Hobbs, New Mexico
(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Gulf Oil Corporation
(Company or Operator)

Bertie Whitmire
(Lease)

Rife Drilling Co, Well No. 6 in the NW $\frac{1}{4}$ NE $\frac{1}{4}$ of Sec. 8,
(Contractor)

T. 20-S, R. 37-E, NMPM., Undesignated Pool, Lea County.

The Dates of this work were as follows: November 26, 1953

Notice of intention to do the work ~~(was)~~ (was not) submitted on Form C-102 on _____, 19____,
(Cross out incorrect words)
and approval of the proposed plan ~~(was)~~ (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Perforated 7" casing from 5175' to 5220' w/4, 1/2" Jet holes per foot.

Witnessed by J. E. Sneed
(Name)

Gulf Oil Corporation
(Company)

Drilling Foreman
(Title)

Approved: _____
OIL CONSERVATION COMMISSION

J. E. Sneed
(Name)

Engineer District I

(Title)

NOV 30 1953

(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name B. F. Taylor

Position Area Prod. Supt.

Representing Gulf Oil Corporation

Address Box 2167, Hobbs, New Mexico