

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06031
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	015340
7. Lease Name or Unit Agreement Name	T ANDERSON
8. Well No.	3
9. Pool Name or Wildcat	MONUMENT; BLINEBRY

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>J</u> : <u>2173</u> Feet From The <u>SOUTH</u> Line and <u>2173</u> Feet From The <u>EAST</u> Line Section <u>8</u> Township <u>20S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3546' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Recomplete to Monument Blinebry ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-23-96; MIRU PU. TOH W/ RODS \$ PUMP. INSTALL BOP & TOH. SDFN.
10-24-96 TIH W/ BIT TO 5228'. TOH TIH W/Cmt Ret. & set 5086'. TEST TBG TO 3000#OK.LOAD & TEST BACKSIDE TO 500#. CHECKING BACKSIDE WHILE PUMPING, NO FLOW OUT CSG.OKSDSFN
10-25-96; D/S SQUEEZE PERFS, 5170'-5235', USING 50-SK'S "C" +.6% D127, +.3% M117, +.2% D46 + 50-SK'S "C" NEAT, SQUEEZE TO 1600#., REVERSE OUT TBG, TOH. SDON. PREP TO DRILL OUT
10-28-96; RU REVERSE UNIT TIH W/BIT. TAG RETAINER 5083'. BREAK CIRC. DRILL 10" OF CEMENT RETAINER. SMALL LEAK.CIRC. CLEAN SDFN.
10-29-96; BREAK CIRC. START DRILLING ON CMT. RET. @5083. DRILL RETAINER & LOWER TOOLS TO 5105' DRILL HARD CEMENT TO 5210' FELL THRU. LOWER TOOLS TO 5254 CIRC. CLEAN TESTED TO 200# FOR 30 MINS. BLED DOWN TO 80#OK.LOST TOTAL OF 15 BBLS.START OUT OF HOLE W/ BIT SDFN
10-30-96; TOH W/ BIT. TIH W/ BIT # 2. TAGGED 5480' DRILL JUNK TO CIBP @5510.DRILL CIBP. TURNED LOOSE & LOST CIRC. & PLUGGED BIT. PUSH CIBP TO 5715-31' ABOVE TD.TOH.SDFN
10-31-96 TIH W/PKR, SN, SET PKR. @ 5530'. PUMP 1k GALS 15%NE FE HCL INTO BLINEBRY PERFS 5606-5696. MAX PRESS=1900 #, MIN PRESS=1000#, AIR=5BPM. FLUSH W/ 40BBLS 2%KCL.ISIP=1000#, VACUUM IN 30 SECS. TIH W/Prod. equip. REM. BOP & NU WEL LHEAD. SDFN
11-1-96; LAYED DOWN RODS. TIH W/rods and pump.HUNG ON RDMO LEFT PUMPING
11-15-96 PUMPING
11-26-96; HOLE IN TBG. MIRU PU.TOH W/ RODS & PUMP INSTALL BOP. TOH W/ TBG.SDFN PREPARE TO LOOK FOR HOLE IN CSG.
11-27-96; TIH W/ PKR. START TESTING CSG. DOWN BACKSIDE @ 5019', 4379', 3729'-DID NOT HOLD. SET PKR @ 3081' AND TEST TO SURFACE HELD 500#. LOWER TOOLS TO 3484'LEAKED OFF. ISOLATE LEAK BETWEEN 3081 AND 3404.PULLED PKR TO 3081'. SDFN
11-28-96 to 12-1-96; SHUT DOWN
12-2-96; SET PKR 3209, 3178, 3146, 3114, 3100 ALL LEAKED OFF W/ CIRC OUT BRADENHEAD 3BPM @ 250#. CSG HELD FROM 3090 TO SURFACE. LEAK IN 7" 3100-3090.TOH W/ PKR. TIH W/OPMJW/ Prod. equip., 7"X2-7/8 23#ARROW TENSION PKR W/ UNLOADER, 108 JTS 2-7/8 TBG.TBG. SET @ 5698', SN @ 5666', PKR @ 5509. SDFN
12-3-96; TIH W/ SAME PUMP & RODS RDMO WELL PUMPING 12-4-96 to 12-9-96 ; PUMPING & TESTING
12-10-96; well parted -shut down--unsuccessful OPT (12/12/96) 0 bopd, 0 bwpd, 8 mcfpd

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE V. Greg Maes TITLE Engineering Assistant DATE 3/12/97
TYPE OR PRINT NAME V. Greg Maes Telephone No. 397-0431

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY JERRY SETTE
CONDITIONS OF APPROVAL, IF ANY: DISTRICT SUPERVISOR

MAR 17 1997
DATE