State of New Mexico Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

F

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06032		
5. Indicate Type of Lease STATE FEE X			

	STATE FEE A		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.		
1000 100 100 100 100 100 100 100 100 10			
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			
(FORM C-101) FOR SUCH PROPOSALS.)			
I. Type of Well:	T. Anderson		
WELL X WELL OTHER			
2. Name of Operator	8. Well No.		
Texaco Producing Inc.	2		
3. Address of Operator	9. Pool name or Wildcat		
P.O. Box 730 Hobbs, New Mexico 88240	Eunice MOnument G.S.A.		
4. Well Location			
Unit Letter I: 1980 Feet From The South Line and	660 Feet From The East Line		
	_		
	NMPM Lea County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>		
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			
11. Check Appropriate Box to Indicate Nature of Notice, R	leport, or Other Data		
NOTICE OF INTENTION TO: SUE	SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT XX		
	G OPNS. PLUG AND ABANDONMENT XX		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND C	G OPNS. PLUG AND ABANDONMENT XX		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT XX		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COTHER: OTHER:	G OPNS. PLUG AND ABANDONMENT XX		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND C	G OPNS. PLUG AND ABANDONMENT XX		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COMMENCE DRILLING OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusivers) SEE RULE 1103.	G OPNS. PLUG AND ABANDONMENT XX		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COMMENCE DRILLING OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusivery) SEE RULE 1103. 1. MIRU w/P&A equipment. Starting date 5-7-91.	EMENT JOB Definition of starting any proposed		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COMMENCE DRILLING OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusivery) SEE RULE 1103. 1. MIRU w/P&A equipment. Starting date 5-7-91. 2. Tagged bottom @ 3404, circ hole w/115 bb1s PPG mud. TOH	EMENT JOB PLUG AND ABANDONMENT XX EMENT JOB uding estimated date of starting any proposed w/tbg.		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COMMENCE DRILLING OTHER:	EMENT JOB PLUG AND ABANDONMENT XX EMENT JOB uding estimated date of starting any proposed w/tbg.		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COMMENCE DRILLING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give pertinent dates, inclusivers) SEE RULE 1103. 1. MIRU w/P&A equipment. Starting date 5-7-91. 2. Tagged bottom @ 3404, circ hole w/115 bb1s PPG mud. TOH was a large of the shots @ 1290. Set cmt ret @ 1252, pumped 150 sx condumped 4 sx cmt on top of cmt. ret. (1232-1290)	EMENT JOB PLUG AND ABANDONMENT XX EMENT JOB ding estimated date of starting any proposed w/tbg. lass "H" cmt into perfs,		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COMMENCE DRILLING OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusivers) SEE RULE 1103. 1. MIRU w/P&A equipment. Starting date 5-7-91. 2. Tagged bottom @ 3404, circ hole w/115 bb1s PPG mud. TOH 3. Perf 4 shots @ 1290. Set cmt ret @ 1252, pumped 150 sx c dumped 4 sx cmt on top of cmt. ret. (1232-1290) 4. WOC 6½ hrs. Survey showed top cmt @ 1200, 20 ft. above starting date starti	EMENT JOB PLUG AND ABANDONMENT XX EMENT JOB ding estimated date of starting any proposed w/tbg. lass "H" cmt into perfs,		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COMMENCE DRILLING OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusivers) SEE RULE 1103. 1. MIRU w/P&A equipment. Starting date 5-7-91. 2. Tagged bottom @ 3404, circ hole w/115 bb1s PPG mud. TOH 3. Perf 4 shots @ 1290. Set cmt ret @ 1252, pumped 150 sx c dumped 4 sx cmt on top of cmt. ret. (1232-1290) 4. WOC 6½ hrs. Survey showed top cmt @ 1200, 20 ft. above s 3/4 BPM @ 750#.	EMENT JOB PLUG AND ABANDONMENT XX EMENT JOB widing estimated date of starting any proposed w/tbg. lass "H" cmt into perfs, hoe. Pumped into 9 5/8" csg		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusivork) SEE RULE 1103. 1. MIRU w/P&A equipment. Starting date 5-7-91. 2. Tagged bottom @ 3404, circ hole w/115 bb1s PPG mud. TOH was a larged 4 shots @ 1290. Set cmt ret @ 1252, pumped 150 sx condumped 4 sx cmt on top of cmt. ret. (1232-1290) 4. WOC 6½ hrs. Survey showed top cmt @ 1200, 20 ft. above so 3/4 BPM @ 750#. 5. Spt 100 sx class "H" cmt from 700' to surf dn 9 5/8" csg	EMENT JOB PLUG AND ABANDONMENT XX EMENT JOB widing estimated date of starting any proposed w/tbg. lass "H" cmt into perfs, hoe. Pumped into 9 5/8" csg		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusiver). SEE RULE 1103. 1. MIRU w/P&A equipment. Starting date 5-7-91. 2. Tagged bottom @ 3404, circ hole w/115 bbls PPG mud. TOH 3. Perf 4 shots @ 1290. Set cmt ret @ 1252, pumped 150 sx cdumped 4 sx cmt on top of cmt. ret. (1232-1290) 4. WOC 6½ hrs. Survey showed top cmt @ 1200, 20 ft. above s 3/4 BPM @ 750#. 5. Spt 100 sx class "H" cmt from 700' to surf dn 9 5/8" csg 6. Spt 40 sx class "H" cmt from 289' to 189'.	EMENT JOB PLUG AND ABANDONMENT XX EMENT JOB widing estimated date of starting any proposed w/tbg. lass "H" cmt into perfs, hoe. Pumped into 9 5/8" csg		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusiver). SEE RULE 1103. 1. MIRU w/P&A equipment. Starting date 5-7-91. 2. Tagged bottom @ 3404, circ hole w/115 bbls PPG mud. TOH of the starting date set on top of cmt. ret @ 1252, pumped 150 sx condumped 4 sx cmt on top of cmt. ret. (1232-1290) 4. WOC 6½ hrs. Survey showed top cmt @ 1200, 20 ft. above so 3/4 BPM @ 750#. 5. Spt 100 sx class "H" cmt from 700' to surf dn 9 5/8" csg 6. Spt 40 sx class "H" cmt from 289' to 189'. 7. Spt 10 sx class "H" cmt from 30' to surface.	EMENT JOB PLUG AND ABANDONMENT XX EMENT JOB widing estimated date of starting any proposed with g. lass "H" cmt into perfs, hoe. Pumped into 9 5/8" csg Left 250# on 9 5/8" csg.		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusiver). SEE RULE 1103. 1. MIRU w/P&A equipment. Starting date 5-7-91. 2. Tagged bottom @ 3404, circ hole w/115 bbls PPG mud. TOH 3. Perf 4 shots @ 1290. Set cmt ret @ 1252, pumped 150 sx cdumped 4 sx cmt on top of cmt. ret. (1232-1290) 4. WOC 6½ hrs. Survey showed top cmt @ 1200, 20 ft. above s 3/4 BPM @ 750#. 5. Spt 100 sx class "H" cmt from 700' to surf dn 9 5/8" csg 6. Spt 40 sx class "H" cmt from 289' to 189'.	EMENT JOB PLUG AND ABANDONMENT XX EMENT JOB widing estimated date of starting any proposed with g. lass "H" cmt into perfs, hoe. Pumped into 9 5/8" csg Left 250# on 9 5/8" csg.		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusiver). SEE RULE 1103. 1. MIRU w/P&A equipment. Starting date 5-7-91. 2. Tagged bottom @ 3404, circ hole w/115 bbls PPG mud. TOH of the starting date set on top of cmt. ret @ 1252, pumped 150 sx condumped 4 sx cmt on top of cmt. ret. (1232-1290) 4. WOC 6½ hrs. Survey showed top cmt @ 1200, 20 ft. above so 3/4 BPM @ 750#. 5. Spt 100 sx class "H" cmt from 700' to surf dn 9 5/8" csg 6. Spt 40 sx class "H" cmt from 289' to 189'. 7. Spt 10 sx class "H" cmt from 30' to surface.	EMENT JOB PLUG AND ABANDONMENT XX EMENT JOB widing estimated date of starting any proposed with g. lass "H" cmt into perfs, hoe. Pumped into 9 5/8" csg Left 250# on 9 5/8" csg.		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusiver). SEE RULE 1103. 1. MIRU w/P&A equipment. Starting date 5-7-91. 2. Tagged bottom @ 3404, circ hole w/115 bbls PPG mud. TOH of the starting date set on top of cmt. ret @ 1252, pumped 150 sx condumped 4 sx cmt on top of cmt. ret. (1232-1290) 4. WOC 6½ hrs. Survey showed top cmt @ 1200, 20 ft. above so 3/4 BPM @ 750#. 5. Spt 100 sx class "H" cmt from 700' to surf dn 9 5/8" csg 6. Spt 40 sx class "H" cmt from 289' to 189'. 7. Spt 10 sx class "H" cmt from 30' to surface.	EMENT JOB PLUG AND ABANDONMENT XX EMENT JOB widing estimated date of starting any proposed with g. lass "H" cmt into perfs, hoe. Pumped into 9 5/8" csg Left 250# on 9 5/8" csg.		

I hereby certify that the information above is true and complete to the best of my knowledg	e and belief.	
SIONATURE TICLY	mæ Engineer's Assistant	DATE5-13-91
TYPE OR PRINT NAME M.C. Duncan		ТЕLЕРНО ВЕ NO. 393-7191
(This space for State Use)	M. & GAD LINE LOUIS	'n
APPROVED BY & WAURILE	. TITLE	- DATE
CONDITIONS OF APPROVAL, IF ANY:		