

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

O+2 - NMOCD
 1 - File
 1 - Engineer (PB)
 1 - Foreman

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
6. Farm or Lease Name T. Anderson
9. Well No. 2
10. Field and Pool, or Wildcat Monument GB-SA
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO ABILE OR TO OPEN OR DRILL BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
 Getty Oil Company

3. Address of Operator
 P. O. Box 730, Hobbs, New Mexico 88240

4. Location of Well
 UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM
East THE 8 LINE, SECTION 20-S TOWNSHIP 37-E RANGE 37-E NMPM.

15. Elevation (Show whether DF, KT, GR, etc.)
 3550' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T. Anderson Well No. 2

- Rig up pulling unit and install BOP.
- POH with 2 7/8" tubing and submersible pump.
- GIH with 2 7/8" workstring, collars and bit.
- Drill out well to original TD, 3880'. (Retainers @ 3695', @3760', CIBP @ 3793', top @ 3783').
- POH with workstring, collars and bit.
- Rig up perforating company.
- GIH with casing gun and perforate 1 spf the following interval: 3704'-25' and 3766'-80' (37 holes).
- POH with casing gun.
- GIH with 2 7/8" workstring and treating packer.
- Set packer at \pm 3690'.
- Acidize perfs 3704'-25', 3766'-80', and open hole section 3804'-30', as per service company's recommendations.
- POH with tubing and packer.
- GIH with 2 7/8" tubing and submersible equipment. Set pump \pm 3530'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale R. Crockett TITLE Area Superintendent DATE 4/21/81

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: