

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Samedan Oil Corporation				Address 2207 Wilco Bldg. Midland, Texas			
Lease Byers	Well No. 2	Unit Letter G	Section 3	Township 19-S	Range 38-E		
Date Work Performed 1-31-63		Pool Hobbs		County Lea			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain): **Remove packer and installed pumping equipment.**
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Reservoir pressure decline and considerable increase of water production prevented well from producing by natural flow. Guiberson type C-1 production packer was removed from the well and pumping equipment was installed to produce well by artificial lift. 2 3/8" tubing was set at 4118' and a 2" x 1 1/2" x 12' sub-surface pump was set at 4119'.

Witnessed by A. W. Batte	Position District Foreman	Company Samedan Oil Corporation
------------------------------------	-------------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA


D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name G. W. Putnam
Title	Position Production Superintendent
Date	Company Samedan Oil Corporation