

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)


Name of Company Samadan Oil Corporation		Address 2207 Wilco Bldg. - Midland, Texas				
Lease Byers	Well No. 4	Unit Letter H	Section 3	Township 19-S	Range 38-E	
Date Work Performed 1-20-63	Pool Hobbs	County Lea				

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☒ Other (Explain): **Set Packer**
☐ Plugging ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

2" x 5 $\frac{1}{2}$ " Baker "AD" Tension Packer was run on tubing and set at 4118' in attempt to establish natural flow of well and eliminate reservoir pressure on oil string casing. Attempt to establish natural flow was unsuccessful. Well continues to produce by means of artificial lift.

Witnessed by A. W. Batte		Position District Foreman		Company Samadan Oil Corporation		
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY						
ORIGINAL WELL DATA						
D F Elev.	T D	P B T D		Producing Interval	Completion Date	
Tubing Diameter		Tubing Depth		Oil String Diameter	Oil String Depth	
Perforated Interval(s)						
Open Hole Interval			Producing Formation(s)			
RESULTS OF WORKOVER						
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						
OIL CONSERVATION COMMISSION				I hereby certify that the information given above is true and complete to the best of my knowledge.		
Approved by 				Name G. W. Putnam		
Title				Position Production Superintendent		
Date				Company Samadan Oil Corporation		