

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (FORM O-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name
2. Name of Operator Amoco Production Company		8. Name of Lease Name South Hobbs (GSA) Unit
3. Address of Operator P. O. Box 68, Hobbs, NM 88240		9. Well No. 36
4. Location of well UNIT LETTER <u>F</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>19-S</u> RANGE <u>38-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Hobbs GSA
11. Elevation (Show whether DF, RT, GR, etc.) 3617' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to increase production by acidizing as follows:

Pull rods, pump, & tubing. Run packer & tubing to 4000'. Run a temp base log from TD of 4227' to 4000'. Lower & set packer at 4115'. Acidize as follows at 3-5 BPM:
Pump 5400 gals of 20% HCL mixed with 600 gals of Nalco Chemicals Visco 1176 in 4 equal stages. In each of stages 1, 2, & 3, pump approx 300 lbs of a 50/50 mix of graded rock salt & benzoic acid flakes in 300 gals of 30# gelled brine. Flush acid to perfs with water. Run a temp survey. Raise packer & set at 4000'. Acidize as follows at 3-5 BPM:
Pump 2000 gals of 20% HCL mixed with 200 gals of Nalco Chemicals Visco 1176 in 2 equal stages. Pump 400 lbs of a 50/50 mix of graded rock salt & benzoic acid flakes in 400 gals of 30# gelled brine in first stage. Flush to perfs with water. Run a temp survey. Pull packer & tubing. Return well to production.

0+4-NMOCD, H 1-Hou 1-Susp 1-CLF

I, hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy L. Ferman TITLE Assist. Admin. Analyst DATE 11-23-81

APPROVED BY Orig. Signed By Jerry Sexton TITLE : DATE NOV 28 1981

CONDITIONS OF APPROVAL, IF ANY Dist 1, Supv.