

Stensland - Byers #29-A NE
3-19-38.

We did not receive SG 103x
106 for the $10\frac{3}{4}$ " pipe for this
well and I did not receive
notice of their intention to
test this pipe due to a
misunderstanding of
superintendent for the
Stensland. He was under
the impression that we
did not require this test
for this string. Although
they tested it for their
own satisfaction.

J. D. Hunter.