State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION	
DISTRICT I	2040 Pa	acheco St.	WELL API NO. 30-025-07590
P.O. Box 1980, Hobbs, NM 88240	Santa Fe,	NM 87505	
DISTRICT II			5. Indicate Type of Lease FED STATE X FEE
811 S. 1st Street, Artesia, NM 88210			6. State Oil & Gas Lease No.
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410			0. State Off & Gas Lease 140.
	OTICES AND REPORTS ON WEI	116	
			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI"		RMIT"	1. Deast Name of One Agreement Name
	M C-101 FOR SUCH PROPOSALS.)		SOUTH HOBBS (G/SA) UNIT
1. Type of Well:			
Oil Well	Gas Well Other IN	JECTOR (SHUT IN)	8. Well No. 48
2. Name of Operator			8. Well No. 48
OCCIDENTAL PERMIAN LTI 3. Address of Operator	D		9. Pool name or Wildcat HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS	. NM 88240 505/39	7-8200	(,
4. Well Location 3300 North			
Unit Letter J: 1980	Feet From The SOUTH	Line and 2310 Fee	et From The EAST Line
			
Section 3	Township 19S	Range 38E	NMPM LEA County
	10. Elevation (Show whether DF, RF 3607' GL	KB, RT GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON X	CHANGE PLANS	COMMENCE DRILLING OF	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEME	NT JOB
FULL OR ALTER CASING		0.101110 1201 1210 021112	
	[OTHER.	
OTHER:		OTHER:	
	ntions (Clearly state all pertinent details, an		estimated date of starting any proposed work)
12. Describe Proposed or Completed Opera			estimated date of starting any proposed work)
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before joint and the proposed of Completed Opera SEE RULE 1103.	b. (393-6161)		
12. Describe Proposed or Completed Opera SEE RULE 1103.	b. (393-6161)		
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. 1. 2. 4.5" liner from 3773' to 4250'. 3. RIH w/4.5" CIBP and set @406.	b. (393-6161) Baker Lok-Set @4066'.		
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. In 2. 4.5" liner from 3773' to 4250'. RIH w/4.5" CIBP and set @4004. Circ csg w/pkr fluid.	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'.		
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. 1. 2. 4.5" liner from 3773' to 4250'. 3. RIH w/4.5" CIBP and set @406.	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'.		
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. In 2. 4.5" liner from 3773' to 4250'. RIH w/4.5" CIBP and set @4004. Circ csg w/pkr fluid.	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'.		
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. In 2. 4.5" liner from 3773' to 4250'. RIH w/4.5" CIBP and set @4004. Circ csg w/pkr fluid.	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'.		estimated date of starting any proposed work) Solution of the starting any proposed work) Solution of the starting any proposed work)
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. In 2. 4.5" liner from 3773' to 4250'. RIH w/4.5" CIBP and set @4004. Circ csg w/pkr fluid.	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'.		JUL 2000 ED
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. In 2. 4.5" liner from 3773' to 4250'. RIH w/4.5" CIBP and set @4004. Circ csg w/pkr fluid.	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'.		
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. In 2. 4.5" liner from 3773' to 4250'. RIH w/4.5" CIBP and set @4004. Circ csg w/pkr fluid.	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'.		JUL 2000 ED
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. In 2. 4.5" liner from 3773' to 4250'. 3. RIH w/4.5" CIBP and set @4004. Circ csg w/pkr fluid. 5. Test csg to 500 psi for 30 min and set 2.	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'. and chart for the NMOCD.	d give pertinent dates, including	JUL 2000 ED
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before job 1. POH w/Injection equipment. I 2. 4.5" liner from 3773' to 4250'. 3. RIH w/4.5" CIBP and set @4004. Circ csg w/pkr fluid. 5. Test csg to 500 psi for 30 min a set complete the complete set of the	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'. and chart for the NMOCD.	d give pertinent dates, including	JUL 2000 ED
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. In 2. 4.5" liner from 3773' to 4250'. 3. RIH w/4.5" CIBP and set @4004. Circ csg w/pkr fluid. 5. Test csg to 500 psi for 30 min and set complete in the information above. SIGNATURE	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'. and chart for the NMOCD. is true and complete to the best of my know	d give pertinent dates, including	CH DATE 07/11/2002
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. In 2. 4.5" liner from 3773' to 4250'. 3. RIH w/4.5" CIBP and set @4004. 4. Circ csg w/pkr fluid. 5. Test csg to 500 psi for 30 min and analysis of the second property of the	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'. and chart for the NMOCD.	d give pertinent dates, including	JUL 2000 ED
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. In 2. 4.5" liner from 3773' to 4250'. 3. RIH w/4.5" CIBP and set @4004. Circ csg w/pkr fluid. 5. Test csg to 500 psi for 30 min and set complete in the information above. SIGNATURE	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'. and chart for the NMOCD. is true and complete to the best of my know	rledge and belief.	CH DATE 07/11/2002 TELEPHONE NO. 505/397-8206
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. In 2. 4.5" liner from 3773' to 4250'. 3. RIH w/4.5" CIBP and set @4004. 4. Circ csg w/pkr fluid. 5. Test csg to 500 psi for 30 min and analysis of the second property of the	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'. and chart for the NMOCD. is true and complete to the best of my know	d give pertinent dates, including	CH DATE 07/11/2002 TELEPHONE NO. 505/397-8206
12. Describe Proposed or Completed Opera SEE RULE 1103. Notify the NMOCD 24 hr before join 1. POH w/Injection equipment. In 2. 4.5" liner from 3773' to 4250'. 3. RIH w/4.5" CIBP and set @400'. 4. Circ csg w/pkr fluid. 5. Test csg to 500 psi for 30 min and an	b. (393-6161) Baker Lok-Set @4066'. 60'. Top perf @4202'. and chart for the NMOCD. is true and complete to the best of my know	rledge and belief.	CH DATE 07/11/2002 TELEPHONE NO. 505/397-8206